

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bb63"
    },
    "firstName": "Sayali",
    "type": "CREDITOFFICER",
    "_id": "64bb68b0a87c525d5c04abb3",
    "lastName": "Bangar",
    "mobileNo": "",
    "workMobileNo": "8097275708",
    "email": "cord.racpckalyan@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bb63",
  "branchCode": "000355",
  "type": "BRANCH",
  "name": "RACPC Kalyan",
  "email": "cord.racpckalyan@sbi.co.in",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "address": "Ground Floor, 1 st Floor, Millenium Heights, Opp. Patedar Bhawan
Marriage Hall, Shahad Mohone Road, Shahad, Kalyan (West) - 421 103 \n\n",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "6410199a140f140ffc59b58c",
  "role": "PICKUPPERSON",
  "firstName": "Prakash ",
  "email": "prakashnvetkoli@gmail.com",
  "lastName": "Vetkoli",
  "mobileNo": "9076237689",
  "shortName": "PV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/6410199a140f140ffc59b58c/
profilePhoto_1689054480133_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "67776d60a5477d50e7dbc213",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "AJAY",
  "email": "ajayrewale503@gmail.com",
  "lastName": "REWALE",
  "mobileNo": "9766640171",
  "designation": "",
  "shortName": "AJAY",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/67776d60a5477d50e7dbc213/
profilePhoto_1739252394344_image.jpeg"
},
"rateVerifier": null,
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvanta",
  "mobileNo": "9821518537",
  "designation": "",
  "shortName": "PS",
  "workWithDocumentMaker": "60f915d3f3dd69653a592199",
  "profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
```

```
{
  "value": "IBBI/RV/07/2018/10366",
  "label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
]
],
```

```
    "shortName": "MBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.40466851374814",
  "longitude": "72.85502231717163"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
```

```
"status": true,
"name": "Country",
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Gokhiware",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "6",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "palghar",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Vasai East",
  "label": false
},
"tahsilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahsilNo",
  "value": "",
```

```
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Vasai",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Avadh Township ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
```

```
"name": "Landmark",
"key": "landmark",
"value": "Vidyavikasini School ",
"label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "127/1(P)B",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
}
```



```
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "203",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
```

```
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 401 208",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
}
},
"apfDetails": {
```

```
"buildings": [],
"compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
```

```
"max": "0.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
```

```
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
```



```
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  }
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67d272f2f5937a62ce493fe7",
"ownerName": "Mrs. Nargis Perween ",
"ownerPhoneNo": "7400106659",
"fullAddress": "Residential Flat No. 203, 2nd Floor, Building No 6, Wing - B, Avadh Township , Vidyavikasini School , Village - Gokhiware, Taluka - Vasai, District - palghar, Vasai East, PIN Code - 401 208",
"remark": "",
```

```
"documents": [
  {
    "documentType": {
      "label": "Agreement for sale",
      "value": "60af48bf2ffdf65bcd6585fa"
    },
    "attachConfig": {
      "fromPage": 0,
      "toPage": 0
    },
    "attachInReport": false,
    "inputs": {
      "documentDate": "30/09/2024",
      "from": {
        "value": "Vendor",
        "label": "Vendor"
      },
      "Vendor": "Mr. Vinod Khimji Jethwa",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Mrs. Nargis Perween",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "16779/2024"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1741845205830_AGREEMTNM_0001.pdf",
    "path": "cases/67d272f2f5937a62ce493fe7/
document_1741845205830_AGREEMTNM_0001.pdf",
    "id": "275111",
    "uploadedBy": "6410199a140f140ffc59b58c",
    "createdAt": "Thu Mar 13 2025 05:53:54 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "label": "Other",
      "value": "60ae124eaa6d152c1801b30b"
    },
    "attachConfig": {
      "fromPage": 0,
      "toPage": 0
    }
  }
]
```

```
    },
    "attachInReport": false,
    "inputs": {
      "number": {
        "value": "Document_No",
        "label": "Document No"
      }
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1741845218206_PLAN_COPY_0001_1.pdf",
    "path": "cases/67d272f2f5937a62ce493fe7/
document_1741845218206_PLAN_COPY_0001_1.pdf",
    "id": "497419",
    "uploadedBy": "6410199a140f140ffc59b58c",
    "createdAt": "Thu Mar 13 2025 05:53:54 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "label": "Other",
      "value": "60ae124eaa6d152c1801b30b"
    },
    "attachConfig": {
      "fromPage": 0,
      "toPage": 0
    },
    "attachInReport": false,
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1741845229345_RERA_0001_1.pdf",
    "path": "cases/67d272f2f5937a62ce493fe7/
document_1741845229345_RERA_0001_1.pdf",
    "id": "150330",
    "uploadedBy": "6410199a140f140ffc59b58c",
    "createdAt": "Thu Mar 13 2025 05:53:54 GMT+0000 (Coordinated Universal Time)"
  }
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "014897",
"createdBy": "6410199a140f140ffc59b58c",
"caseHistory": [
  {
    "id": "527532",
```

```
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Mar 13 2025 05:53:54 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Nargis Perween ",
    "phone": "7400106659",
    "ownershipShare": "",
    "email": "",
    "id": "305734"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d2aa89da474c62c8e4f3ba",
    "name": "externalImg_1741859439832_1741859371311_image_0.jpeg",
    "path": "cases/67d272f2f5937a62ce493fe7/externalImg_1741859439832_1741859371311_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d2aa89da474c62c8e4f3bb",
    "name": "externalImg_1741859440774_1741859371311_image_1.jpeg",
    "path": "cases/67d272f2f5937a62ce493fe7/externalImg_1741859440774_1741859371311_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d2aa89da474c62c8e4f3bc",
    "name": "externalImg_1741859441622_1741859371311_image_2.jpeg",
```

```
    "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859441622_1741859371311_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d2aa89da474c62c8e4f3bd",
    "name": "externallmg_1741859442268_1741859371311_image_3.jpeg",
    "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859442268_1741859371311_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d2aa89da474c62c8e4f3be",
    "name": "externallmg_1741859443149_1741859371311_image_4.jpeg",
    "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859443149_1741859371311_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d2aa89da474c62c8e4f3bf",
    "name": "externallmg_1741859444323_1741859371311_image_5.jpeg",
    "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859444323_1741859371311_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d2aa89da474c62c8e4f3c0",
    "name": "externallmg_1741859444822_1741859371311_image_6.jpeg",
    "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859444822_1741859371311_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d2aa89da474c62c8e4f3c1",
    "name": "externallmg_1741859445862_1741859371311_image_7.jpeg",
    "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859445862_1741859371311_image_7.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d2aa89da474c62c8e4f3c2",
  "name": "externallmg_1741859446788_1741859371311_image_8.jpeg",
  "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859446788_1741859371311_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d2aa89da474c62c8e4f3c3",
  "name": "externallmg_1741859447714_1741859371311_image_9.jpeg",
  "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859447714_1741859371311_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d2aa89da474c62c8e4f3c4",
  "name": "externallmg_1741859448883_1741859371311_image_10.jpeg",
  "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859448883_1741859371311_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d2aa89da474c62c8e4f3c5",
  "name": "externallmg_1741859450487_1741859371311_image_11.jpeg",
  "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859450487_1741859371311_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d2aa89da474c62c8e4f3c6",
  "name": "externallmg_1741859451834_1741859371311_image_12.jpeg",
  "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859451834_1741859371311_image_12.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67d2aa89da474c62c8e4f3c7",
      "name": "externallmg_1741859453818_1741859371311_image_13.jpeg",
      "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859453818_1741859371311_image_13.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67d2aa89da474c62c8e4f3c8",
      "name": "externallmg_1741859454088_1741859371311_image_14.jpeg",
      "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859454088_1741859371311_image_14.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67d2aa89da474c62c8e4f3c9",
      "name": "externallmg_1741859457531_1741859371311_image_15.jpeg",
      "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859457531_1741859371311_image_15.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67d2aa89da474c62c8e4f3ca",
      "name": "externallmg_1741859461542_1741859371311_image_16.jpeg",
      "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859461542_1741859371311_image_16.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67d2aa89da474c62c8e4f3cb",
      "name": "externallmg_1741859462972_1741859371311_image_17.jpeg",
      "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859462972_1741859371311_image_17.jpeg",
      "orientation": "portrait"
    },
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d2aa89da474c62c8e4f3cc",
  "name": "externallmg_1741859464418_1741859371311_image_18.jpeg",
  "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859464418_1741859371311_image_18.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d2aa61f5937a62ce499992",
  "name": "externallmg_1741859327489_1741859323793_image_0.jpeg",
  "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859327489_1741859323793_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d2aa61f5937a62ce499993",
  "name": "externallmg_1741859341264_1741859323793_image_1.jpeg",
  "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859341264_1741859323793_image_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d2aa61f5937a62ce499994",
  "name": "externallmg_1741859352091_1741859323793_image_2.jpeg",
  "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859352091_1741859323793_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d2aa61f5937a62ce499995",
  "name": "externallmg_1741859363227_1741859323793_image_3.jpeg",
  "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859363227_1741859323793_image_3.jpeg",
  "orientation": "landscape"
},
{
```



```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67d2aa61f5937a62ce499996",
    "name": "externallmg_1741859375247_1741859323793_image_4.jpeg",
    "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859375247_1741859323793_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67d2aa61f5937a62ce499997",
    "name": "externallmg_1741859385142_1741859323793_image_5.jpeg",
    "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859385142_1741859323793_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67d2aa61f5937a62ce499998",
    "name": "externallmg_1741859393548_1741859323793_image_6.jpeg",
    "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859393548_1741859323793_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67d2aa61f5937a62ce499999",
    "name": "externallmg_1741859394664_1741859323793_image_7.jpeg",
    "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859394664_1741859323793_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67d2aa61f5937a62ce49999a",
    "name": "externallmg_1741859397120_1741859323793_image_8.jpeg",
    "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859397120_1741859323793_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
"status": false,
  "_id": "67d2aa61f5937a62ce49999b",
  "name": "externallmg_1741859400576_1741859323793_image_9.jpeg",
  "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859400576_1741859323793_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d2aa61f5937a62ce49999c",
  "name": "externallmg_1741859406384_1741859323793_image_10.jpeg",
  "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859406384_1741859323793_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d2aa61f5937a62ce49999d",
  "name": "externallmg_1741859408514_1741859323793_image_11.jpeg",
  "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859408514_1741859323793_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d2aa61f5937a62ce49999e",
  "name": "externallmg_1741859409998_1741859323793_image_12.jpeg",
  "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859409998_1741859323793_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d2aa61f5937a62ce49999f",
  "name": "externallmg_1741859412574_1741859323793_image_13.jpeg",
  "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859412574_1741859323793_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
```

```
    "_id": "67d2aa61f5937a62ce4999a0",
    "name": "externallmg_1741859414445_1741859323793_image_14.jpeg",
    "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859414445_1741859323793_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67d2aa61f5937a62ce4999a1",
    "name": "externallmg_1741859418518_1741859323793_image_15.jpeg",
    "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859418518_1741859323793_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67d2aa61f5937a62ce4999a2",
    "name": "externallmg_1741859421673_1741859323793_image_16.jpeg",
    "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859421673_1741859323793_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67d2aa61f5937a62ce4999a3",
    "name": "externallmg_1741859422457_1741859323793_image_17.jpeg",
    "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859422457_1741859323793_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67d2aa61f5937a62ce4999a4",
    "name": "externallmg_1741859423527_1741859323793_image_18.jpeg",
    "path": "cases/67d272f2f5937a62ce493fe7/
externallmg_1741859423527_1741859323793_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67d2aa61f5937a62ce4999a5",
```

```
    "name": "externalImg_1741859424322_1741859323793_image_19.jpeg",
    "path": "cases/67d272f2f5937a62ce493fe7/
externalImg_1741859424322_1741859323793_image_19.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67d2afb8ca9127630f5e7687",
    "name": "externalImg_1741860789849_1741860786902_image_0.jpeg",
    "path": "cases/67d272f2f5937a62ce493fe7/
externalImg_1741860789849_1741860786902_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67d2afb8ca9127630f5e7688",
    "name": "externalImg_1741860791010_1741860786902_image_1.jpeg",
    "path": "cases/67d272f2f5937a62ce493fe7/
externalImg_1741860791010_1741860786902_image_1.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-03-13T05:53:54.289Z",
"updatedAt": "2025-03-13T10:13:12.302Z",
"__v": 0,
"updatedBy": "67776d60a5477d50e7dbc213",
"addressForMap": "",
"caseReferredBy": "6410199a140f140ffc59b58c",
"contactPersonName": "Mrs. Nargis Perween ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"reald": "",
"siteVisitContactNo": "7400106659"
}
```

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			