

```
{
  "typeOfReport": {
    "value": "Structural_Report",
    "label": "Structural Report"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bb50"
    },
    "firstName": "Rupesh",
    "type": "CREDITOFFICER",
    "_id": "658679075b664a64c315b2b3",
    "lastName": "Juvekar",
    "mobileNo": "",
    "workMobileNo": "8169226574",
    "email": "sbi.08586@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "8500000",
    "discussWithPerson": "Rupesh",
    "expectedFees": 4250,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Maharashtra"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bb50",
  "branchCode": "000346",
  "type": "BRANCH",
  "name": "Madam Cama Road Branch Mumbai",
  "email": "sbi.30203@sbi.co.in",
  "mobileNo": "1800 4253800",
  "alternateMobileNo": "",
  "address": "Ground Floor State Bank Annexe Madam Kama Road, Nariman Point,
Mumbai, Maharashtra 400021",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "62727444afd7d55eddee092c",
  "role": "PICKUPPERSON",
  "firstName": "Shantilal",
  "email": "shantilal@vastukala.org",
  "lastName": "Patel",
  "mobileNo": "9969039853",
  "shortName": "SHP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "627362b3afd7d55eddee1ee7",
  "role": "SITEENGINEER",
  "firstName": "Vicky ",
  "email": "vicky@vastukala.org",
  "lastName": "Baor",
  "mobileNo": "9004386288",
  "designation": "",
  "shortName": "VB",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": null,
"checker": null,
"valuers": []
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
}
```

```
"location": {
  "latitude": "18.991166047996042",
  "longitude": "73.1268644314499"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.1268644314499,
    18.991166047996042
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "13/03/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
```

```
"name": "Village",
"key": "village",
"value": "New Panvel",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "3",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
}
```

```
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "7",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sai Leela Apartment",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "16",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
```

```
"key": "wing",
"value": "B",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
}
```

```
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "303",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
```



```
"value": "",
"label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
}
```

```
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
```

```
"presentValueOfFlat": {
  "title": "Present value of the flat (incl. car parking, if provided)",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
}
```

```
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67d27db3f5937a62ce494f99",
"ownerName": "Abhishek Anand Kareker ",
"ownerPhoneNo": "8976333153",
"appAddress": "303B wing \nShree ganesh Co operative Housing society LTD \nsector
16\nNew panvel \nPanvel -410206",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    }
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  }
}
```



```
    },
    "attachInReport": false,
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/67d27db3f5937a62ce494f99/
document_1741847975352_1741847970706_Abhishek_K.pdf",
    "fileName": "document_1741847975352_1741847970706_Abhishek_K.pdf",
    "id": "469730",
    "uploadedBy": "62727444afd7d55eddee092c",
    "createdAt": "Thu Mar 13 2025 06:39:47 GMT+0000 (Coordinated Universal Time)"
  }
],
"caseNumber": "014903",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
  {
    "id": "235793",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Mar 13 2025 06:39:47 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Abhishek Anand Kareker ",
    "phone": "8976333153",
    "ownershipShare": "",
    "email": "",
    "id": "319521"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d90190df28417602ba749f",
    "name": "externallmg_1742274959556_IMG_20250317_396.jpg",
    "path": "cases/67d27db3f5937a62ce494f99/
externallmg_1742274959556_IMG_20250317_396.jpg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d90190df28417602ba74a0",
  "name": "externallmg_1742274959604_IMG_20250317_685.jpg",
  "path": "cases/67d27db3f5937a62ce494f99/
externallmg_1742274959604_IMG_20250317_685.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d90190df28417602ba74a1",
  "name": "externallmg_1742274959616_IMG_20250317_4216.jpg",
  "path": "cases/67d27db3f5937a62ce494f99/
externallmg_1742274959616_IMG_20250317_4216.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d90190df28417602ba74a2",
  "name": "externallmg_1742274959631_IMG_20250317_5564.jpg",
  "path": "cases/67d27db3f5937a62ce494f99/
externallmg_1742274959631_IMG_20250317_5564.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d90190df28417602ba74a3",
  "name": "externallmg_1742274959659_IMG_20250317_5796.jpg",
  "path": "cases/67d27db3f5937a62ce494f99/
externallmg_1742274959659_IMG_20250317_5796.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d90190df28417602ba74a4",
  "name": "externallmg_1742274959665_IMG_20250317_6353.jpg",
  "path": "cases/67d27db3f5937a62ce494f99/
externallmg_1742274959665_IMG_20250317_6353.jpg",
  "orientation": "portrait"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d90190df28417602ba74a5",
    "name": "externallmg_1742274959681_IMG_20250317_6584.jpg",
    "path": "cases/67d27db3f5937a62ce494f99/
externallmg_1742274959681_IMG_20250317_6584.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d90190df28417602ba74a6",
    "name": "externallmg_1742274959717_IMG_20250317_6933.jpg",
    "path": "cases/67d27db3f5937a62ce494f99/
externallmg_1742274959717_IMG_20250317_6933.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d90190df28417602ba74a7",
    "name": "externallmg_1742274959728_IMG_20250317_7216.jpg",
    "path": "cases/67d27db3f5937a62ce494f99/
externallmg_1742274959728_IMG_20250317_7216.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d90190df28417602ba74a8",
    "name": "externallmg_1742274959731_IMG_20250317_7596.jpg",
    "path": "cases/67d27db3f5937a62ce494f99/
externallmg_1742274959731_IMG_20250317_7596.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d90190df28417602ba74a9",
    "name": "externallmg_1742274959756_IMG_20250317_7933.jpg",
    "path": "cases/67d27db3f5937a62ce494f99/
externallmg_1742274959756_IMG_20250317_7933.jpg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d90190df28417602ba74aa",
  "name": "externallmg_1742274959759_IMG_20250317_8259.jpg",
  "path": "cases/67d27db3f5937a62ce494f99/
externallmg_1742274959759_IMG_20250317_8259.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d90190df28417602ba74ab",
  "name": "externallmg_1742274959794_IMG_20250317_8584.jpg",
  "path": "cases/67d27db3f5937a62ce494f99/
externallmg_1742274959794_IMG_20250317_8584.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d90190df28417602ba74ac",
  "name": "externallmg_1742274959798_IMG_20250317_8847.jpg",
  "path": "cases/67d27db3f5937a62ce494f99/
externallmg_1742274959798_IMG_20250317_8847.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d90190df28417602ba74ad",
  "name": "externallmg_1742274959820_IMG_20250317_9128.jpg",
  "path": "cases/67d27db3f5937a62ce494f99/
externallmg_1742274959820_IMG_20250317_9128.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d901a001f1c07601e454af",
  "name": "externallmg_1742274974286_IMG_20250317_9538.jpg",
  "path": "cases/67d27db3f5937a62ce494f99/
externallmg_1742274974286_IMG_20250317_9538.jpg",
  "orientation": "portrait"
},
{
```

```
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "67d901a001f1c07601e454b0",
"name": "externallmg_1742274974317_IMG_20250317_9939.jpg",
"path": "cases/67d27db3f5937a62ce494f99/
externallmg_1742274974317_IMG_20250317_9939.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "67d901a001f1c07601e454b1",
"name": "externallmg_1742274974340_Screenshot_2025031716010875_3d9111e2
d3171bf4882369f490c087b4.jpg",
"path": "cases/67d27db3f5937a62ce494f99/externallmg_1742274974340_Screensh
ot_2025031716010875_3d9111e2d3171bf4882369f490c087b4.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "67d901a001f1c07601e454b2",
"name": "externallmg_1742274974375_IMG_20250317_2365.jpg",
"path": "cases/67d27db3f5937a62ce494f99/
externallmg_1742274974375_IMG_20250317_2365.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "67d901a001f1c07601e454b3",
"name": "externallmg_1742274974380_IMG_20250317_2749.jpg",
"path": "cases/67d27db3f5937a62ce494f99/
externallmg_1742274974380_IMG_20250317_2749.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "67d901a001f1c07601e454b4",
"name": "externallmg_1742274974498_IMG_20250317_3450.jpg",
"path": "cases/67d27db3f5937a62ce494f99/
externallmg_1742274974498_IMG_20250317_3450.jpg",
"orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d901a001f1c07601e454b5",
    "name": "externallmg_1742274974501_IMG_20250317_3853.jpg",
    "path": "cases/67d27db3f5937a62ce494f99/
externallmg_1742274974501_IMG_20250317_3853.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d901a001f1c07601e454b6",
    "name": "externallmg_1742274974520_IMG_20250317_10246.jpg",
    "path": "cases/67d27db3f5937a62ce494f99/
externallmg_1742274974520_IMG_20250317_10246.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d901a001f1c07601e454b7",
    "name": "externallmg_1742274974524_IMG_20250317_10528.jpg",
    "path": "cases/67d27db3f5937a62ce494f99/
externallmg_1742274974524_IMG_20250317_10528.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d901a001f1c07601e454b8",
    "name": "externallmg_1742274974557_IMG_20250317_10750.jpg",
    "path": "cases/67d27db3f5937a62ce494f99/
externallmg_1742274974557_IMG_20250317_10750.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d901a001f1c07601e454b9",
    "name": "externallmg_1742274974588_IMG_20250317_11145.jpg",
    "path": "cases/67d27db3f5937a62ce494f99/
externallmg_1742274974588_IMG_20250317_11145.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "67d901a001f1c07601e454ba",
    "name": "externalimg_1742274974591_IMG_20250317_11508.jpg",
    "path": "cases/67d27db3f5937a62ce494f99/
externalimg_1742274974591_IMG_20250317_11508.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d901a001f1c07601e454bb",
    "name": "externalimg_1742274974634_IMG_20250317_11813.jpg",
    "path": "cases/67d27db3f5937a62ce494f99/
externalimg_1742274974634_IMG_20250317_11813.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d901a001f1c07601e454bc",
    "name": "externalimg_1742274974650_IMG_20250317_160957.jpg",
    "path": "cases/67d27db3f5937a62ce494f99/
externalimg_1742274974650_IMG_20250317_160957.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d901a001f1c07601e454bd",
    "name": "externalimg_r_1742274974802_IMG20250317232254.jpg",
    "path": "cases/67d27db3f5937a62ce494f99/
externalimg_r_1742274974802_IMG20250317232254.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d901a001f1c07601e454be",
    "name": "externalimg_r_1742274974754_IMG20250317232247.jpg",
    "path": "cases/67d27db3f5937a62ce494f99/
externalimg_r_1742274974754_IMG20250317232247.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
```

```

"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-03-13T06:39:47.979Z",
"updatedAt": "2025-03-18T05:16:16.341Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 303, 3rd Floor, Wing - B, Sai Leela Apartment, Plot
No. 7, Sector 16, Village - New Panvel, State - Maharashtra, India",
"updatedBy": "6006d4ce5080a310ac1fdfc2",
"addressForMap": "",
"caseReferredBy": "62727444afd7d55eddee092c",
"contactPersonName": "Abhishek Anand Kareker ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"rerald": "",
"siteVisitContactNo": "8976333153"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			