

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": true,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856ba0e"
    },
    "firstName": "Anju",
    "type": "CREDITOFFICER",
    "_id": "665d91c259496f15880eb07f",
    "lastName": "Kakkar",
    "mobileNo": "",
    "workMobileNo": "9935817392",
    "email": "BullionExchange.MumbaiSouth@bankofindia.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "8500000",
    "discussWithPerson": "Anju",
    "expectedFees": 4250,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180a",
  "type": "BANK",
  "name": "Bank of India",
  "displayName": "Bank of India",
  "initial": "BOI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856ba0e",
  "branchCode": "000036",
  "type": "BRANCH",
  "name": "Bullion Exchange Branch",
  "email": "BullionExchange.MumbaiSouth@bankofindia.co.in",
  "mobileNo": "02267443302",
  "alternateMobileNo": "",
  "address": "Bullion Exchange185, Sheikh Memon St, L K Market, Chippi Chawl,
Kalbadevi, Mumbai, Maharashtra 400002",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e2f4336576061dae469362",
  "zoneName": "Mumbai South Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "62727444afd7d55eddee092c",
  "role": "PICKUPPERSON",
  "firstName": "Shantilal",
  "email": "shantilal@vastukala.org",
  "lastName": "Patel",
  "mobileNo": "9969039853",
  "shortName": "SHP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f949ce45132d6a6bddbcc3",
  "role": "SITEENGINEER",
  "firstName": "Tushar ",
  "email": "tusharbhuwad90@gmail.com",
  "lastName": "Bhuwad",
  "mobileNo": "9082053889",
  "designation": "",
  "shortName": "TSB",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f949ce45132d6a6bddbcc3/
profilePhoto_1668058314746_WhatsApp_Image_20221110_at_105931_AM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91b6f344e052188ffd1fc",
  "role": "MAKER",
  "firstName": "Jayaraja",
  "email": "jayaraja@vastukala.org",
```

```
"lastName": "Acharya",
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "6084131a13f01f158c6ea1f3",
    "PANNo": "AEAPC7114Q",
    "role": "VALUER",
    "firstName": "Sharadkumar",
    "fatherName": "Baburao",
    "email": "cmd@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9422171100",
    "designation": "CMD",
    "registrationNo": [
      {
        "title": {
          "value": "Wealth_Tax",
          "label": "Wealth Tax"
        }
      }
    ]
  }
],
```

```
    "_id": "6084131a13f01f158c6ea1f4",
    "number": "[N]C.C.I.T/I -14/52/2008-09"
  }
],
  "shortName": "SBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.068566102584878",
  "longitude": "72.82428467946771"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.82428467946771,
    19.068566102584878
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "13/03/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2025-03-17",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2025-03-18",
      "remark": "MANUAL_IN_TASK"
    }
  ],
  {
```

```
    "status": "COMPLETED",
    "dateTime": "2025-03-18",
    "remark": "MANUAL_IN_TASK"
  },
  {
    "status": "COMPLETED",
    "dateTime": "2025-03-18",
    "remark": "MANUAL_IN_TASK"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Bandra",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "4",
```

```
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Bandra (West), Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Andheri",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
```

```
"name": "Building Name",
"key": "buildingName",
"value": "Benston A Co-op. Hsg. Soc. Ltd.",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Village Danda, Sherly Rajan Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Off Carter Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
}
```



```
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "1488, 1490 & 1498",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "402",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
```

```
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 050",
  "label": false
},
}
```

```

"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "flooring": {
    "value": "Vitrified_tiles_flooring",
    "label": "Vitrified tiles flooring"
  },
  "doors": {
    "value": "Teak_wood_door_frame_with_flush_shutters",
    "label": "Teak wood door frame with flush shutters"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",

```

```
"label": "Urban"
},
"townplanApprovedByList": {
  "value": "MCGM",
  "label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": " Internal Road & Moon Craft Building",
  "west": "Internal Road & Mahati Wellness",
  "south": "'B' Wing of Benston B CHSL & Internal Road",
  "east": "Seagull Apartments"
},
"asPerDocumentAgreement": {
  "north": "Information not available",
  "west": "Information not available",
  "south": "Information not available",
  "east": "Information not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "-",
    "east": "-",
    "south": "-",
    "west": "-"
  },
  "asPerDocument": {
    "north": "-",
    "east": "-",
    "south": "-",
    "west": "-"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
```

```

    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "(2 BHK flat converted into 3 BHK, Kitchen in Flat No. Flat No. 401.)",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received it may be assumed that the construction is as per Sanctioned Plan.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "1)\tAs per Site Inspection, Residential Flat No. 401 & 402 are internally amalgamated by having separate entrances. Two flats are internally amalgamated to form a single flat but can be demarcated individually.<br/>\n2)\tFor the purpose of valuation, we have considered area as per documents of Flat No. 402 only. <br/>\n3)\tAs per site inspection kitchen of flat No. 402 converted into bedroom. <br/>\n",
  "depreciationPercentage": "49.500000000000001",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "41762.5",
  "depreciatedBuildingRate": "1262.4999999999998"
},
"igrRate": {
  "propertyName": " Residential Flat",
  "rate": "452350",
  "landRate": "244050",
  "igrImage": "cases/67d28d1dda474c62c8e4d18a/igr_1742478845333_Image.png",
  "squareMeterGuideLineRate": "452350.00",
  "squareFeetGuideLineRate": "42025.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "67",
  "rate": "35639.00",
  "squareFeetGuideLineRate": "35639.00",
  "squareMeterGuideLineRate": "383611.00"
}

```

```
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Information not available",
  "taxPaidHolderName": "Information not available",
  "taxAmount": "Information not available",
  "electricityServiceConnectionNo": "Information not available",
  "meterCardHolderName": "Information not available",
  "undividedAreaOfLandAsPerSaleDeed": "Information not available",
  "floorSpaceIndex": "As per MCGM norms",
  "tenantName": "",
  "maintenanceOfFlat": "Vacant flat in normal condition"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
}
```

```
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Garage No. 2 on Ground Floor ",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "1992",
  "fullDate": "1/1/1992"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
}
```

```
},
"protAgainstNatDis": {
  "value": "Designed_as_per_I.S._codes",
  "label": "Designed as per I.S. codes"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
```



```
"ageOfBuilding": "33",
"totalLifeBuilding": "60",
"estimatedAge": "27",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "4",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "3"
},
"finalPlinthArea": {
  "area": "850.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Draft Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/67d28d1dda474c62c8e4d18a/
routeMap_1742453351492_Image.png",
    "routeLat": "19.068361",
    "routeLng": "72.823972",
    "stationName": "Khar Road",
    "routeDistance": "2.5 km ",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
"locationMapImg": [
  {
    "id": "4aqwe",
    "name": "4aqwe",
    "image": "cases/67d28d1dda474c62c8e4d18a/
routeMap_1742453193086_Image.png"
```

```
}
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "35498550.00",
  "finalValue": "35498550.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValueDocument": null,
  "purchaseValueDocument": null,
  "bookValue": "0"
},
"outward": {
```

```
"status": true,
"remark": "SYSTEMGENERATED",
"datetime": "2025-03-21T07:43:21.493Z",
"date": "Fri Mar 21 2025 07:43:21 GMT+0000 (Coordinated Universal Time)",
"number": "2311173",
"dayCount": "13",
"monthCount": "370",
"generatedBy": "64cde526dc9f3034f3fefa49"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "30293150.00",
  "selectedBuildUpValue": "850.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
```

```
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "67da3fd5700ebc6884947c41",
      "name": "externallmg_r_1742356436921_2025031822432600.jpg",
      "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742356436921_2025031822432600.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "67da3fd5700ebc6884947c3f",
      "name": "externallmg_r_1742356436942_2025031822432601.jpg",
      "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742356436942_2025031822432601.jpg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "67da3f94df28417602bb3ba1",
      "name": "externallmg_r_1742356368240_TimePhoto_20250317_165955.jpg",
      "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742356368240_TimePhoto_20250317_165955.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "67da3fd5700ebc6884947c43",
      "name": "externallmg_r_1742356436983_2025031822432702.jpg",
      "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742356436983_2025031822432702.jpg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "67da3fd5700ebc6884947c4c",
      "name": "externallmg_r_1742356437177_2025031822425100.jpg",
      "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742356437177_2025031822425100.jpg",
      "orientation": "portrait"
    }
  ]
}
```

```
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "67dcfe3eeeda08cd80b605d4",
    "name": "Living Room",
    "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742536252471_2025031822425000.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67dcfe3eeeda08cd80b605dd",
    "name": "Living Room",
    "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742536252610_2025031822425300.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67dcfe3eeeda08cd80b605de",
    "name": "Living Room",
    "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742536252543_2025031822425200.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67dcfe3eeeda08cd80b605e1",
    "name": "Living Room",
    "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742536252633_2025031822425302.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67dcfe4f5e615e2c6a407d2f",
    "name": "Living Room",
    "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742536269736_2025031822425401.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
```

```
    "_id": "67dcfe4f5e615e2c6a407d31",
    "name": "Living Room",
    "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742536269800_2025031822425500.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "67dcfe4f5e615e2c6a407d2e",
    "name": "Living Room",
    "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742536269756_2025031822425402.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67dcfe3eeeda08cd80b605db",
    "name": "Living Room",
    "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742536252511_2025031822425101.jpg",
    "orientation": "landscape"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "48987.00",
    "max": "53922.00"
  },
  "builtUpRateRange": {
    "min": "40823.00",
    "max": "44935.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  }
}
```



```
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": [],
  "totalValue": 0,
  "additionTotalValue": 0,
  "lessTotalValue": 0,
  "presentMarketValue": 0
},
"taskStatus": {
  "SITE_INSPECTION": false,
```

```
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "850.00",
"empanelmentNo": [
  "KZO/CR/19-20/582"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67d28d1dda474c62c8e4d18a",
"ownerName": "Mr. Naval Dowlatram Relwani",
"ownerPhoneNo": "9819011487",
"appAddress": "401\nThe Benston A co operative Housing society \nsherli Ranjan
Road \nBandar w\nMumbai 400 050",
"remark": " purchaser Name Anjali Jagdish \nseller Sunder Dowlatram Belwani \n
\nother Documents visit time ",
"documents": [
  {
    "documentType": {
      "label": "Draft Agreement for sale",
      "value": "60ae1256aa6d152c1801b330"
    },
    "attachConfig": {
      "fromPage": 0,
      "toPage": 0
    }
  }
]
```

```
},
"attachInReport": false,
"inputs": {
  "from": {
    "value": "Vendor",
    "label": "Vendor"
  },
  "Vendor": "Mr. Naval Dowlatram Relwani",
  "to": {
    "value": "Purchaser",
    "label": "Purchaser"
  },
  "Purchaser": "Mrs. Anjali Jagdish Murpana"
},
"isHardCopy": false,
"displayStatus": true,
"id": "154748",
"path": "cases/67d28d1dda474c62c8e4d18a/
document_1742356213516_Benston_402_1.pdf",
"fileName": "document_1742356213516_Benston_402_1.pdf"
},
{
  "documentType": {
    "label": "Occupancy Certificate",
    "value": "60ae124baa6d152c1801b2fd"
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  },
  "attachInReport": false,
  "inputs": {
    "documentDate": "01/04/1992",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CE/8091/BSII/AH"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1742533809337_OC.pdf",
```

```
"path": "cases/67d28d1dda474c62c8e4d18a/document_1742533809337_OC.pdf",
"id": "825178",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Fri Mar 21 2025 05:10:09 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "014912",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
{
  "id": "251398",
  "title": "Create Lead",
  "description": "Create Lead",
  "datetime": "Thu Mar 13 2025 07:45:33 GMT+0000 (Coordinated Universal Time)"
}
],
"owners": [
{
  "name": "Mr. Naval Dowlatram Relwani",
  "phone": "9819011487",
  "ownershipShare": "",
  "email": "",
  "id": "549612"
}
],
"proposePurchasers": [
{
  "name": "Mrs. Anjali Jagdish Murpana",
  "phone": "",
  "email": "",
  "ownershipShare": "",
  "panNo": "",
  "aadharNo": ""
}
],
"siteInspection": [],
"composition": [
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "239941",
  "name": "Living Room",
  "length": "11.33",
  "length1": "11",

```

```
"length2": "4",
"width": "18.83",
"width1": "18",
"width2": "10",
"totalArea": "213.44",
"images": [],
"extraAreas": [],
"finalArea": "213.44"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Passage",
  "length": "7.75",
  "length1": "7",
  "length2": "9",
  "width": "5.00",
  "width1": "5",
  "width2": "00",
  "totalArea": "38.75",
  "images": [],
  "extraAreas": [],
  "finalArea": "38.75"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "10.25",
  "length1": "10",
  "length2": "3",
  "width": "12.33",
  "width1": "12",
  "width2": "4",
  "totalArea": "126.42",
  "images": [],
  "extraAreas": [],
  "finalArea": "126.42"
},
{
  }
```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "3",
"name": "Toilet",
"length": "7.33",
"length1": "7",
"length2": "4",
"width": "3.58",
"width1": "3",
"width2": "7",
"totalArea": "26.28",
"images": [],
"extraAreas": [],
"finalArea": "26.28"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "12.00",
  "length1": "12",
  "length2": "00",
  "width": "7.25",
  "width1": "7",
  "width2": "3",
  "totalArea": "87.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "87.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "14.08",
  "length1": "14",
  "length2": "1",
  "width": "10.25",
```

```
"width1": "10",
"width2": "3",
"totalArea": "144.35",
"images": [],
"extraAreas": [],
"finalArea": "144.35"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "4.58",
  "length1": "4",
  "length2": "7",
  "width": "7.92",
  "width1": "7",
  "width2": "11",
  "totalArea": "36.28",
  "images": [],
  "extraAreas": [],
  "finalArea": "36.28"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Draft Agreement for sale",
      "value": "60ae1256aa6d152c1801b330"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "652855",
    "selectAreaTypeDocument": "Built_Up",
    "totalAreaDocument": "850",
    "squareMeterArea": "78.97",
    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
    "docBuiltupPercentage": "",
    "docSaleablePercentage": "0",
```



```
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
"carpetArea": {
"area": "510.00",
"squareMeterArea": "47.38",
"expectedRate": "53921.57",
"percentage": ""
},
"builtUpArea": {
"area": "612.00",
"squareMeterArea": "56.86",
"expectedRate": "44934.64",
"percentage": "20"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printInReport": true,
"_id": "67dc14401c2f4c2c6b7bdcb3",
"property": "Residential Flat ",
"area": "510",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "27500000",
"expectedRate": "53921.57",
"builtUpExpectedRate": "44934.64",
"image": "cases/67d28d1dda474c62c8e4d18a/
indicator_1742475194654_Image.png",
"squareMeter": "47.38",
"id": "487485"
},
{
"carpetArea": {
"area": "1000.00",
```

```
"squareMeterArea": "92.90",
"expectedRate": "50000.00",
"percentage": ""
},
"builtUpArea": {
  "area": "1200.00",
  "squareMeterArea": "111.48",
  "expectedRate": "41666.67",
  "percentage": "20"
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printlnReport": true,
"_id": "67dc14401c2f4c2c6b7bdcb4",
"property": "Residential Flat ",
"area": "1000",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "50000000",
"expectedRate": "50000.00",
"builtUpExpectedRate": "41666.67",
"image": "cases/67d28d1dda474c62c8e4d18a/
indicator_1742475239802_Image.png",
"squareMeter": "92.90",
"id": "354577"
},
{
  "carpetArea": {
    "area": "600.00",
    "squareMeterArea": "55.74",
    "expectedRate": "48986.67",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "720.00",
    "squareMeterArea": "66.89",
    "expectedRate": "40822.22",
    "percentage": "20"
  }
}
```

```
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printlnReport": true,
"_id": "67dd18b1eeda08cd80b63fd1",
"property": "Residential Flat ",
"area": "600",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "29392000",
"expectedRate": "48986.67",
"builtUpExpectedRate": "40822.22",
"image": "cases/67d28d1dda474c62c8e4d18a/
indicator_1742475287029_Image.png",
"squareMeter": "55.74",
"id": "529617"
},
{
  "carpetArea": {
    "area": "1017.00",
    "squareMeterArea": "94.48",
    "expectedRate": "49164.21",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1220.40",
    "squareMeterArea": "113.38",
    "expectedRate": "40970.17",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "67dc14401c2f4c2c6b7bdcb6",
```

```
"property": "Residential Flat ",
"area": "1017",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "50000000",
"expectedRate": "49164.21",
"builtUpExpectedRate": "40970.17",
"image": "cases/67d28d1dda474c62c8e4d18a/
indicator_1742475323026_Image.png",
"squareMeter": "94.48",
"id": "626046"
}
],
"externallImages": [
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67da3f94df28417602bb3b9a",
  "name": "externallmg_1742356367535_Screenshot_2025031821570212_3d9111e2
d3171bf4882369f490c087b4.jpg",
  "path": "cases/67d28d1dda474c62c8e4d18a/externallmg_1742356367535_Screens
hot_2025031821570212_3d9111e2d3171bf4882369f490c087b4.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67da3fff01f1c07601e54f43",
  "name": "externallmg_r_1742356479113_2025031822404602.jpg",
  "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742356479113_2025031822404602.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67da3fff01f1c07601e54f45",
  "name": "externallmg_r_1742356479141_2025031822404700.jpg",
  "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742356479141_2025031822404700.jpg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67da3fff01f1c07601e54f46",
  "name": "externallmg_r_1742356479166_2025031822404701.jpg",
  "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742356479166_2025031822404701.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67da4028700ebc6884947cbb",
  "name": "externallmg_r_1742356519231_IMG20250318223714.jpg",
  "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742356519231_IMG20250318223714.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67da4028700ebc6884947cbc",
  "name": "externallmg_r_1742356519166_IMG20250318223705.jpg",
  "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742356519166_IMG20250318223705.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67dcfe3eeeda08cd80b605d4",
  "name": "externallmg_r_1742536252471_2025031822425000.jpg",
  "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742536252471_2025031822425000.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67dcfe3eeeda08cd80b605d5",
  "name": "externallmg_r_1742536252465_2025031822424902.jpg",
  "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742536252465_2025031822424902.jpg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67dcfe3eeda08cd80b605d6",
    "name": "externallmg_r_1742536252445_2025031822424901.jpg",
    "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742536252445_2025031822424901.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67dcfe3eeda08cd80b605d7",
    "name": "externallmg_r_1742536252420_2025031822424900.jpg",
    "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742536252420_2025031822424900.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67dcfe3eeda08cd80b605d8",
    "name": "externallmg_r_1742536252483_2025031822425001.jpg",
    "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742536252483_2025031822425001.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67dcfe3eeda08cd80b605d9",
    "name": "externallmg_r_1742536252503_2025031822425100.jpg",
    "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742536252503_2025031822425100.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67dcfe3eeda08cd80b605da",
    "name": "externallmg_r_1742536252539_2025031822425102.jpg",
    "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742536252539_2025031822425102.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "67dcfe3eeeda08cd80b605db",
  "name": "externalimg_r_1742536252511_2025031822425101.jpg",
  "path": "cases/67d28d1dda474c62c8e4d18a/
externalimg_r_1742536252511_2025031822425101.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67dcfe3eeeda08cd80b605dc",
  "name": "externalimg_r_1742536252545_2025031822425201.jpg",
  "path": "cases/67d28d1dda474c62c8e4d18a/
externalimg_r_1742536252545_2025031822425201.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67dcfe3eeeda08cd80b605dd",
  "name": "externalimg_r_1742536252610_2025031822425300.jpg",
  "path": "cases/67d28d1dda474c62c8e4d18a/
externalimg_r_1742536252610_2025031822425300.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67dcfe3eeeda08cd80b605de",
  "name": "externalimg_r_1742536252543_2025031822425200.jpg",
  "path": "cases/67d28d1dda474c62c8e4d18a/
externalimg_r_1742536252543_2025031822425200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67dcfe3eeeda08cd80b605df",
  "name": "externalimg_r_1742536252578_2025031822425202.jpg",
  "path": "cases/67d28d1dda474c62c8e4d18a/
externalimg_r_1742536252578_2025031822425202.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "67dcfe3eeeda08cd80b605e0",
    "name": "externalimg_r_1742536252613_2025031822425301.jpg",
    "path": "cases/67d28d1dda474c62c8e4d18a/
externalimg_r_1742536252613_2025031822425301.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67dcfe3eeeda08cd80b605e1",
    "name": "externalimg_r_1742536252633_2025031822425302.jpg",
    "path": "cases/67d28d1dda474c62c8e4d18a/
externalimg_r_1742536252633_2025031822425302.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67dcfe4f5e615e2c6a407d2e",
    "name": "externalimg_r_1742536269756_2025031822425402.jpg",
    "path": "cases/67d28d1dda474c62c8e4d18a/
externalimg_r_1742536269756_2025031822425402.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67dcfe4f5e615e2c6a407d2f",
    "name": "externalimg_r_1742536269736_2025031822425401.jpg",
    "path": "cases/67d28d1dda474c62c8e4d18a/
externalimg_r_1742536269736_2025031822425401.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67dcfe4f5e615e2c6a407d30",
    "name": "externalimg_r_1742536269725_2025031822425400.jpg",
    "path": "cases/67d28d1dda474c62c8e4d18a/
externalimg_r_1742536269725_2025031822425400.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67dcfe4f5e615e2c6a407d31",
```



```
    "name": "externallmg_r_1742536269800_2025031822425500.jpg",
    "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742536269800_2025031822425500.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67dcfe4f5e615e2c6a407d32",
    "name": "externallmg_r_1742536269811_2025031822432600.jpg",
    "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742536269811_2025031822432600.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67dcfe4f5e615e2c6a407d33",
    "name": "externallmg_r_1742536269826_2025031822432601.jpg",
    "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742536269826_2025031822432601.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67dcfe4f5e615e2c6a407d34",
    "name": "externallmg_r_1742536269872_2025031822432701.jpg",
    "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742536269872_2025031822432701.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67dcfe4f5e615e2c6a407d35",
    "name": "externallmg_r_1742536269852_2025031822432700.jpg",
    "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742536269852_2025031822432700.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67dcfe4f5e615e2c6a407d36",
    "name": "externallmg_r_1742536269898_2025031822432702.jpg",
```

```
    "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742536269898_2025031822432702.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67dcfe4f5e615e2c6a407d37",
    "name": "externallmg_r_1742536269954_2025031822432801.jpg",
    "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742536269954_2025031822432801.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67dcfe4f5e615e2c6a407d38",
    "name": "externallmg_r_1742536269974_2025031822432802.jpg",
    "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742536269974_2025031822432802.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67dcfe4f5e615e2c6a407d39",
    "name": "externallmg_r_1742536269913_2025031822432800.jpg",
    "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742536269913_2025031822432800.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67dcfe4f5e615e2c6a407d3a",
    "name": "externallmg_r_1742536269999_TimePhoto_20250317_152650.jpg",
    "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742536269999_TimePhoto_20250317_152650.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67dcfe4f5e615e2c6a407d3b",
    "name": "externallmg_r_1742536270026_TimePhoto_20250317_165917.jpg",
    "path": "cases/67d28d1dda474c62c8e4d18a/
externallmg_r_1742536270026_TimePhoto_20250317_165917.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67dcfe61eeda08cd80b60653",
  "name": "externalImg_r_1742536288403_TimePhoto_20250317_170026.jpg",
  "path": "cases/67d28d1dda474c62c8e4d18a/
externalImg_r_1742536288403_TimePhoto_20250317_170026.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67dcfe61eeda08cd80b60654",
  "name": "externalImg_r_1742536288478_TimePhoto_20250317_170102.jpg",
  "path": "cases/67d28d1dda474c62c8e4d18a/
externalImg_r_1742536288478_TimePhoto_20250317_170102.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67dcfe61eeda08cd80b60655",
  "name": "externalImg_r_1742536288429_TimePhoto_20250317_170028.jpg",
  "path": "cases/67d28d1dda474c62c8e4d18a/
externalImg_r_1742536288429_TimePhoto_20250317_170028.jpg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation Sheet NEW.xlsx",
    "filename": "1742478886548_Calculation_Sheet_NEW.xlsx",
    "path": "cases/67d28d1dda474c62c8e4d18a/
processingDocuments/1742478886548_Calculation_Sheet_NEW.xlsx",
    "size": "2795107",
    "createdAt": "Thu Mar 20 2025 13:54:48 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "OC.pdf",
    "filename": "1742478888034_OC.pdf",
    "path": "cases/67d28d1dda474c62c8e4d18a/
processingDocuments/1742478888034_OC.pdf",
```

```
"size": "1817102",
"createdAt": "Thu Mar 20 2025 13:54:48 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "64cde526dc9f3034f3fefa49"
},
{
  "originalname": "Notice at site (1).jpg",
  "filename": "1742536413015_Notice_at_site_1.jpg",
  "path": "cases/67d28d1dda474c62c8e4d18a/
processingDocuments/1742536413015_Notice_at_site_1.jpg",
  "size": "43420",
  "createdAt": "Fri Mar 21 2025 05:53:33 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Notice at site (3).jpg",
  "filename": "1742536413016_Notice_at_site_3.jpg",
  "path": "cases/67d28d1dda474c62c8e4d18a/
processingDocuments/1742536413016_Notice_at_site_3.jpg",
  "size": "46363",
  "createdAt": "Fri Mar 21 2025 05:53:33 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Notice at site (4).jpg",
  "filename": "1742536413019_Notice_at_site_4.jpg",
  "path": "cases/67d28d1dda474c62c8e4d18a/
processingDocuments/1742536413019_Notice_at_site_4.jpg",
  "size": "42905",
  "createdAt": "Fri Mar 21 2025 05:53:33 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Notice at site (5).jpg",
  "filename": "1742536413062_Notice_at_site_5.jpg",
  "path": "cases/67d28d1dda474c62c8e4d18a/
processingDocuments/1742536413062_Notice_at_site_5.jpg",
  "size": "51705",
  "createdAt": "Fri Mar 21 2025 05:53:33 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Notice at site (6).jpg",
  "filename": "1742536413064_Notice_at_site_6.jpg",
  "path": "cases/67d28d1dda474c62c8e4d18a/
processingDocuments/1742536413064_Notice_at_site_6.jpg",
  "size": "47587",
```

```
"createdAt": "Fri Mar 21 2025 05:53:33 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "OC.pdf",
  "filename": "1742536413068_OC.pdf",
  "path": "cases/67d28d1dda474c62c8e4d18a/
processingDocuments/1742536413068_OC.pdf",
  "size": "1817102",
  "createdAt": "Fri Mar 21 2025 05:53:33 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Site Details.jpg",
  "filename": "1742536413173_Site_Details.jpg",
  "path": "cases/67d28d1dda474c62c8e4d18a/
processingDocuments/1742536413173_Site_Details.jpg",
  "size": "1759566",
  "createdAt": "Fri Mar 21 2025 05:53:33 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Sketch & Dimention.jpg",
  "filename": "1742536413446_Sketch__Dimention.jpg",
  "path": "cases/67d28d1dda474c62c8e4d18a/
processingDocuments/1742536413446_Sketch__Dimention.jpg",
  "size": "1257757",
  "createdAt": "Fri Mar 21 2025 05:53:33 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Draft Agreement - Flat No. 402.pdf",
  "filename": "1742536433311_Draft_Agreement__Flat_No_402.pdf",
  "path": "cases/67d28d1dda474c62c8e4d18a/
processingDocuments/1742536433311_Draft_Agreement__Flat_No_402.pdf",
  "size": "118258",
  "createdAt": "Fri Mar 21 2025 05:53:53 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
```

```
    "role": "FRONTDESK",
    "firstName": "Rashmi",
    "lastName": "Jadhav",
    "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "67dbc2c9eeda08cd80b4e2b4",
  "note": "Value given for confirmation ",
  "taskId": "67d2ad50ca9127630f5e71e4",
  "createdAt": "2025-03-20T07:24:57.023Z"
}
],
"createdAt": "2025-03-13T07:45:33.469Z",
"updatedAt": "2025-03-21T07:44:07.611Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "64cde526dc9f3034f3fefa49",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 402, 4th Floor, Wing - A, Benston A Co-op. Hsg.
Soc. Ltd., Village Danda, Sherly Rajan Road, Off Carter Road, Village - Bandra, Taluka
- Andheri, District - Mumbai Suburban, Bandra (West), Mumbai, PIN - 400 050, State -
Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "62727444afd7d55eddee092c",
"contactPersonName": "Mr. Mohammad Mistr",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "Mrs. Anjali Jagdish Murpana",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Property Agent",
"reral": "",
"siteVisitContactNo": "9967646112",
"buildingServicesRate": "2500",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Draft Agreement for sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
```

```
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 850.00",
"flatRate": "43000",
"landOtherRate": "40500",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"reportGeneratedDate": "Fri Mar 21 2025 04:16:27 GMT+0000 (Coordinated Universal
Time)",
"siteVisitDate": "2025-03-18",
"briefDescOfProperty": "3 Bedroom + Living Room + Passage + 2 Toilet",
"carpetTotal": "672.52",
"otherCarpetTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "807.02",
"finalCarpetArea": "672.52",
"finalSalableArea": "807.02",
"salablePercentage": "0",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"extendOfSiteRemark": "",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00",
"siteMeasurementRemark": ""
```

Name	Length	Width	Total
Composition :			
Living Room	11'4"	18'10"	213.44
Passage	7'9"	5'00"	38.75
Bedroom	10'3"	12'4"	126.42
Toilet	7'4"	3'7"	26.28
Bedroom	12'00"	7'3"	87.00
Bedroom	14'1"	10'3"	144.35
Toilet	4'7"	7'11"	36.28
Other Composition :			