

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "firstName": "Avinash",
    "type": "CREDITOFFICER",
    "_id": "675287fccfae933db22a82ff",
    "email": "avinash.bhosle.ssl@gmail.com",
    "lastName": "Bhosle",
    "mobileNo": "",
    "workMobileNo": "9167389229"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "Avinash",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Maharashtra"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1722582806298_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9462345132d6a6bddb9d5",
  "role": "SITEENGINEER",
  "firstName": "Dashrath ",
  "email": "dasrat.jaiswar1234@gmail.com",
  "lastName": "Jaiswar",
  "mobileNo": "9987305468",
  "designation": "",
  "shortName": "DFJ",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
  "lastName": "Rasam",
```

```
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
      "title": {
        "label": "IBBI"
      },
      "_id": "60af80072ffdf65bcd658651",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  {

```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.064387209523208",
  "longitude": "72.88246892636498"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.88246892636498,
    19.064387209523208
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2025-03-17",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2025-03-19",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2025-03-18",
      "remark": "MANUAL_IN_TASK"
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
```

```
"key": "country",
"value": "Country - India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Kurla III",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "8",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
```

```
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla ",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Nehru Nagar Shree Krupa Co-Op. Hsg. Soc. Ltd. ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Nehru Nagar",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
```



```
"value": "",
"label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Sayba Residency",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "229 & 267",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "6(Part)",
  "label": true
},
"blockNo": {
```

```
"status": false,
"name": "Block No",
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "803",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
```

```
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 024",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Kurla (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Aluminium_Sliding_Windows_with_window_grills",
    "label": "Aluminium Sliding Windows with window grills"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
}
```

```
"finishing": {
  "value": "Cement_Plastering_+_POP_Finish",
  "label": "Cement Plastering + POP Finish"
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MHADA",
    "label": "MHADA"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Ruparel Pride ",
    "west": "Internal Road",
    "south": "Nalla",
    "east": "Internal Road"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available ",
    "west": "Details not available ",
    "south": "Details not available ",
    "east": "Details not available "
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Marginal Space ",
      "east": "Flat No. 804",
      "south": "Flat No. 806",
      "west": "Lift"
    },
    "asPerDocument": {
```

```
    "north": "Details not available ",
    "east": "Details not available ",
    "south": "Details not available ",
    "west": "Details not available "
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received, we assumed that
the construction is as per Sanction Plan.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "0",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "buildingServicesDepreciatedRate": "0",
  "depreciatedCostOfConstruction": "21000.00",
  "depreciatedBuildingRate": "3000"
},
"igrRate": {
  "propertyName": "Residential",
```

```
"rate": "125170",
"landRate": "49960",
"igrImage": "cases/67d2e2feb0f7a2cb91a2964e/igr_1742212696578_Image.png",
"squareMeterGuideLineRate": "131429.00",
"squareFeetGuideLineRate": "12210.00"
},
"igrFinalRate": {
  "floorRatePercentage": "5",
  "depreciationPercentage": "0",
  "rate": "125170.00",
  "squareMeterGuideLineRate": "131429.00",
  "squareFeetGuideLineRate": "12210.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "25,000/- (Expected rental income per month)",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Details not available ",
  "meterCardHolderName": "Details not available ",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
  "floorSpaceIndex": "As per MHADA norms ",
  "tenantName": "",
  "maintenanceOfFlat": "Good "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
```

```
"roof": {
  "value": "rcc_Slab",
  "label": "R. C. C. Slab"
},
"partitions": {
  "value": "6\"_Thk._Brick_Masonry",
  "label": "6\" Thk. Brick Masonery"
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Stilt Car Parking Space ",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2023",
  "fullDate": "1/1/2023"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
}
```

```
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
```



```
"value": "1",
"label": "Yes"
},
"groundStilt": {
"value": "stilt",
"label": "Stilt"
},
"yearOfConstructionAsPer": {
"value": "as_per_occupancy_certificate",
"label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "58",
"ageOfBuilding": "2",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "18",
"flatFloorNo": "8",
"noOfLifts": "3",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
"area": "561.00",
"areaType": "Built Up",
"measurementType": "Sq. Ft.",
"areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
"routeMapDetail": {
"routeMapImg": "cases/67d2e2feb0f7a2cb91a2964e/
routeMap_1742299194891_Image.png",
"routeLat": "19.062278",
"routeLng": "72.885000",
"stationName": "Kurla ",
"routeDistance": "700 Mtrs. ",
"routeStation": {
"value": "Railway_Station",
"label": "Railway Station"
}
}
},
"finalLatLng": {
"coordinates": [
0,
0
```

```
    ],
    "type": "Point"
  },
  "showLocation": {
    "latlng": false,
    "finallatlng": false
  },
  "locationMapImg": [
    {
      "id": "m4cvkp",
      "name": "m4cvkp",
      "image": "cases/67d2e2feb0f7a2cb91a2964e/
routeMap_1742299007322_Image.png"
    }
  ]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
```

```
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "10710000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "10710000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
```

```
"guidelineDetails": {
  "finalGuidelineValue": "6849810.00",
  "selectedBuildUpValue": "561.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "67daa104df28417602bbbf54",
      "name":
"externallmg_1742381314760_WhatsApp_Image_20250319_at_41449_PM_1.jpeg",
      "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742381314760_WhatsApp_Image_20250319_at_41449_PM_1.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "67d7e575700ebc68849334e2",
      "name": "externallmg_1742202225188_1742202219431_image_3.jpeg",
      "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742202225188_1742202219431_image_3.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "67d7e575700ebc68849334e4",
      "name": "externallmg_1742202225237_1742202219431_image_5.jpeg",
      "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742202225237_1742202219431_image_5.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "67d7e575700ebc68849334e6",
      "name": "externallmg_1742202225651_1742202219431_image_7.jpeg",
      "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742202225651_1742202219431_image_7.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "67d7e575700ebc68849334ed",
```

```
    "name": "externallmg_1742202226800_1742202219431_image_14.jpeg",
    "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742202226800_1742202219431_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67d7e575700ebc68849334ec",
    "name": "externallmg_1742202226391_1742202219431_image_13.jpeg",
    "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742202226391_1742202219431_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67d7e575700ebc68849334e7",
    "name": "externallmg_1742202225733_1742202219431_image_8.jpeg",
    "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742202225733_1742202219431_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67daa104df28417602bbbf55",
    "name":
"externallmg_1742381314800_WhatsApp_Image_20250319_at_41449_PM.jpeg",
    "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742381314800_WhatsApp_Image_20250319_at_41449_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67daa104df28417602bbbf54",
    "name":
"externallmg_1742381314760_WhatsApp_Image_20250319_at_41449_PM_1.jpeg",
    "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742381314760_WhatsApp_Image_20250319_at_41449_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "67daa104df28417602bbbf56",
    "name":
"externallmg_1742381314838_WhatsApp_Image_20250319_at_41450_PM_1.jpeg",
    "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742381314838_WhatsApp_Image_20250319_at_41450_PM_1.jpeg",
```

```
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "20724.00",
    "max": "23438.00"
  },
  "builtUpRateRange": {
    "min": "18840.00",
    "max": "21307.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```



```
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
}
```

```
"isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": [],
  "totalValue": 0,
  "additionTotalValue": 0,
  "lessTotalValue": 0,
  "presentMarketValue": 0
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
}
```

```
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "510.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67d2e2feb0f7a2cb91a2964e",
"ownerName": "Smt. Smita Vilas Chavan & Mr. Vinit Vilas Chavan ",
"ownerPhoneNo": "9004217873",
"appAddress": "Flat no. 803, 8th Floor, Wing A, Syaba Residency, Nehru Nagar Shree
Krupa CHS, Kurla East",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement for sale",
      "value": "60af48bf2ffdf65bcd6585fa"
    },
    "attachConfig": {
      "fromPage": 0,
      "toPage": 0
    },
    "attachInReport": false,
    "inputs": {
      "documentDate": "07/03/2025",
      "from": {
        "value": "Vendor",
        "label": "Vendor"
      },
      "Vendor": "Shri. Rajendra Sitaram Kadam ",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      },
      "Purchasers": "Smt. Smita Vilas Chavan & Mr. Vinit Vilas Chavan ",
      "number": {
        "value": "No",
        "label": "No"
      }
    }
  },

```

```
    "No": "4942 / 2025"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "608384",
  "path": "cases/67d2e2feb0f7a2cb91a2964e/
document_1741873908204_1741873905522_CamScanner_03132025_163622.pdf",
  "fileName":
"document_1741873908204_1741873905522_CamScanner_03132025_163622.pdf"
},
{
  "documentType": {
    "label": "Occupancy Certificate",
    "value": "60ae124baa6d152c1801b2fd"
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  },
  "attachInReport": false,
  "inputs": {
    "documentDate": "21/04/2023",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Housing_And_Area_Development_Authority",
      "label": "Maharashtra Housing And Area Development Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "MH / EE / (B.P) / GM / MHADA - 22 / 538 / 2023"
},
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1742296060316_1641842.pdf",
  "path": "cases/67d2e2feb0f7a2cb91a2964e/
document_1742296060316_1641842.pdf",
  "id": "798182",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Tue Mar 18 2025 11:07:40 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "Commencement Certificate",
    "value": "60ae1247aa6d152c1801b2ea"
  },
}
```

```
"attachConfig": {
  "fromPage": 0,
  "toPage": 0
},
"attachInReport": false,
"inputs": {
  "documentDate": "26/04/2020",
  "nameOfApprovingAuthority": {
    "value": "Maharashtra_Housing_And_Area_Development_Authority",
    "label": "Maharashtra Housing And Area Development Authority"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "MH / EE / (B.P) / GM / MHADA - 22 / 538 / 2020"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1742297415499_1641842.pdf",
"path": "cases/67d2e2feb0f7a2cb91a2964e/
document_1742297415499_1641842.pdf",
"id": "106328",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Tue Mar 18 2025 11:30:16 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "RERA Certificate",
    "value": "60ae129faa6d152c1801b47d"
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  },
  "attachInReport": false,
  "inputs": {
    "documentDate": "15/01/2021",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
}
```

```
    "No": "P51800027913"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1742297485659_349447.pdf",
  "path": "cases/67d2e2feb0f7a2cb91a2964e/
document_1742297485659_349447.pdf",
  "id": "300766",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Tue Mar 18 2025 11:31:25 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "014917",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "351144",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Mar 13 2025 13:51:58 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Smt. Smita Vilas Chavan & Mr. Vinit Vilas Chavan ",
    "phone": "9004217873",
    "ownershipShare": "",
    "email": "",
    "id": "358801"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "426410",
    "name": "Living Room",
    "length": "15.42",
    "length1": "15",
    "length2": "5",
    "width": "9.75",
    "width1": "9",
```

```
"width2": "9",
"totalArea": "150.31",
"images": [],
"extraAreas": [],
"finalArea": "150.31"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Passage",
  "length": "17.33",
  "length1": "17",
  "length2": "4",
  "width": "2.92",
  "width1": "2",
  "width2": "11",
  "totalArea": "50.55",
  "images": [],
  "extraAreas": [],
  "finalArea": "50.55"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "9.00",
  "length1": "9",
  "length2": "00",
  "width": "6.75",
  "width1": "6",
  "width2": "9",
  "totalArea": "60.75",
  "images": [],
  "extraAreas": [],
  "finalArea": "60.75"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  }
}
```

```
},
  "id": "3",
  "name": "WC",
  "length": "6.67",
  "length1": "6",
  "length2": "8",
  "width": "3.92",
  "width1": "3",
  "width2": "11",
  "totalArea": "26.11",
  "images": [],
  "extraAreas": [],
  "finalArea": "26.11"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "9.25",
  "length1": "9",
  "length2": "3",
  "width": "9.25",
  "width1": "9",
  "width2": "3",
  "totalArea": "85.56",
  "images": [],
  "extraAreas": [],
  "finalArea": "85.56"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "10.92",
  "length1": "10",
  "length2": "11",
  "width": "9.92",
  "width1": "9",
  "width2": "11",
  "totalArea": "108.26",
```



```
"images": [],
"extraAreas": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "_id": "67d95cc801f1c07601e5075a",
    "name": "Extra",
    "extraAreaType": "Add",
    "length": "5.00",
    "length1": "5",
    "length2": "00",
    "width": "1.00",
    "width1": "1",
    "width2": "00",
    "totalArea": "5.00"
  }
],
"finalArea": "113.26"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bathroom",
  "length": "3.67",
  "length1": "3",
  "length2": "8",
  "width": "6.42",
  "width1": "6",
  "width2": "5",
  "totalArea": "23.53",
  "images": [],
  "extraAreas": [],
  "finalArea": "23.53"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement for sale",
    }
  }
]
```

```
    "value": "60af48bf2ffdf65bcd6585fa"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "606225",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "510",
  "squareMeterArea": "47.38",
  "docFinalBuiltUp": "561",
  "docFinalBuiltUpSquareMeter": "52.118",
  "docBuiltupPercentage": "10",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "546.00",
      "squareMeterArea": "50.73",
      "expectedRate": "21062.27",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "600.60",
      "squareMeterArea": "55.80",
      "expectedRate": "19147.52",
      "percentage": "10"
    },
    "saleableArea": {
      "area": "",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
      "percentage": ""
    }
  },
  "printlnReport": true,
  "_id": "67d80e77700ebc6884937abb",
  "property": "Sayba Residency, Kurla East",
  "area": "546",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
```

```
"areaType": "Carpet",
"floor": "-",
"source": "Nobroker.com",
"expectedPrice": "11500000",
"expectedRate": "21062.27",
"builtUpExpectedRate": "19147.52",
"image": "cases/67d2e2feb0f7a2cb91a2964e/
indicator_1742212364738_Image.png",
"squareMeter": "50.73",
"id": "336923"
},
{
  "carpetArea": {
    "area": "448.00",
    "squareMeterArea": "41.62",
    "expectedRate": "23437.50",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "492.80",
    "squareMeterArea": "45.78",
    "expectedRate": "21306.82",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "67d80e77700ebc6884937abc",
  "property": "Sayba Residency, Kurla East",
  "area": "448",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "10",
  "source": "https://www.99acres.com/",
  "expectedPrice": "10500000",
  "expectedRate": "23437.50",
  "builtUpExpectedRate": "21306.82",
  "image": "cases/67d2e2feb0f7a2cb91a2964e/
indicator_1742212433639_Image.png",
  "squareMeter": "41.62",
```

```
"id": "841237"
},
{
  "carpetArea": {
    "area": "608.00",
    "squareMeterArea": "56.49",
    "expectedRate": "20723.68",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "668.80",
    "squareMeterArea": "62.13",
    "expectedRate": "18839.71",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "67d80e77700ebc6884937abd",
  "property": "Nehru Nagar, Kurla East",
  "area": "608",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "2",
  "source": "Index_no.2",
  "expectedPrice": "12600000",
  "expectedRate": "20723.68",
  "builtUpExpectedRate": "18839.71",
  "image": "cases/67d2e2feb0f7a2cb91a2964e/
indicator_1742212517531_Image.png",
  "squareMeter": "56.49",
  "id": "135854"
}
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d7e575700ebc68849334e2",
    "name": "externallmg_1742202225188_1742202219431_image_3.jpeg",
```

```
    "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742202225188_1742202219431_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d7e575700ebc68849334e3",
    "name": "externallmg_1742202225206_1742202219431_image_4.jpeg",
    "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742202225206_1742202219431_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d7e575700ebc68849334e4",
    "name": "externallmg_1742202225237_1742202219431_image_5.jpeg",
    "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742202225237_1742202219431_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d7e575700ebc68849334e5",
    "name": "externallmg_1742202225634_1742202219431_image_6.jpeg",
    "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742202225634_1742202219431_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d7e575700ebc68849334e6",
    "name": "externallmg_1742202225651_1742202219431_image_7.jpeg",
    "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742202225651_1742202219431_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d7e575700ebc68849334e7",
    "name": "externallmg_1742202225733_1742202219431_image_8.jpeg",
    "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742202225733_1742202219431_image_8.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d7e575700ebc68849334e8",
  "name": "externallmg_1742202225775_1742202219431_image_9.jpeg",
  "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742202225775_1742202219431_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d7e575700ebc68849334e9",
  "name": "externallmg_1742202225814_1742202219431_image_10.jpeg",
  "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742202225814_1742202219431_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d7e575700ebc68849334ea",
  "name": "externallmg_1742202226040_1742202219431_image_11.jpeg",
  "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742202226040_1742202219431_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d7e575700ebc68849334eb",
  "name": "externallmg_1742202226196_1742202219431_image_12.jpeg",
  "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742202226196_1742202219431_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d7e575700ebc68849334ec",
  "name": "externallmg_1742202226391_1742202219431_image_13.jpeg",
  "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742202226391_1742202219431_image_13.jpeg",
  "orientation": "portrait"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d7e575700ebc68849334ed",
    "name": "externallmg_1742202226800_1742202219431_image_14.jpeg",
    "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742202226800_1742202219431_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d7e575700ebc68849334ee",
    "name": "externallmg_1742202227053_1742202219431_image_15.jpeg",
    "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742202227053_1742202219431_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d7e575700ebc68849334ef",
    "name": "externallmg_1742202227416_1742202219431_image_16.jpeg",
    "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742202227416_1742202219431_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d7e575700ebc68849334f0",
    "name": "externallmg_1742202227725_1742202219431_image_17.jpeg",
    "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742202227725_1742202219431_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d7e575700ebc68849334f1",
    "name": "externallmg_1742202228083_1742202219431_image_18.jpeg",
    "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742202228083_1742202219431_image_18.jpeg",
    "orientation": "portrait"
  },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d7e575700ebc68849334f2",
  "name": "externallmg_1742202228762_1742202219431_image_19.jpeg",
  "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742202228762_1742202219431_image_19.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d7e54cdf28417602b9e944",
  "name": "externallmg_1742202187249_1742202184278_image_0.jpeg",
  "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742202187249_1742202184278_image_0.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d7e54cdf28417602b9e945",
  "name": "externallmg_1742202187803_1742202184279_image_1.jpeg",
  "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742202187803_1742202184279_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d7e54cdf28417602b9e946",
  "name": "externallmg_1742202187883_1742202184279_image_2.jpeg",
  "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742202187883_1742202184279_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d7e58f700ebc6884933575",
  "name": "externallmg_1742202253040_1742202238136_image_0.jpeg",
  "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742202253040_1742202238136_image_0.jpeg",
  "orientation": "portrait"
},
{
```



```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67d7e58f700ebc6884933576",
    "name": "externallmg_1742202254209_1742202238136_image_1.jpeg",
    "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742202254209_1742202238136_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67daa104df28417602bbbf54",
    "name":
"externallmg_1742381314760_WhatsApp_Image_20250319_at_41449_PM_1.jpeg",
    "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742381314760_WhatsApp_Image_20250319_at_41449_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67daa104df28417602bbbf55",
    "name":
"externallmg_1742381314800_WhatsApp_Image_20250319_at_41449_PM.jpeg",
    "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742381314800_WhatsApp_Image_20250319_at_41449_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67daa104df28417602bbbf56",
    "name":
"externallmg_1742381314838_WhatsApp_Image_20250319_at_41450_PM_1.jpeg",
    "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742381314838_WhatsApp_Image_20250319_at_41450_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67daa104df28417602bbbf57",
    "name":
"externallmg_1742381314851_WhatsApp_Image_20250319_at_41450_PM.jpeg",
    "path": "cases/67d2e2feb0f7a2cb91a2964e/
externallmg_1742381314851_WhatsApp_Image_20250319_at_41450_PM.jpeg",
```

```
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname":
"1741163957653_1730802342675_1710338010411_Calculation.xlsx",
    "filename": "1742212721211_1741163957653_1730802342675_1710338010411_C
alculation.xlsx",
    "path": "cases/67d2e2feb0f7a2cb91a2964e/processingDocuments/1742212721211
_1741163957653_1730802342675_1710338010411_Calculation.xlsx",
    "size": "1221587",
    "createdAt": "Mon Mar 17 2025 11:58:41 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "igr_6757.pdf",
    "filename": "1742212721238_igr_6757.pdf",
    "path": "cases/67d2e2feb0f7a2cb91a2964e/
processingDocuments/1742212721238_igr_6757.pdf",
    "size": "128294",
    "createdAt": "Mon Mar 17 2025 11:58:41 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-03-13T13:51:58.214Z",
"updatedAt": "2025-03-19T12:05:08.543Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 803, 8th Floor, Wing - A, Nehru Nagar Shree Krupa
Co-Op. Hsg. Soc. Ltd. , Sayba Residency, Nehru Nagar, Village - Kurla III, Kurla (East),
Taluka - Kurla , District - Mumbai Suburban, PIN - 400 024, State - Maharashtra,
Country - India",
"updatedBy": "60f915d3f3dd69653a592199",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Smt. Smita Vilas Chavan ",
"email": "",
"isExternal": "false",
```

```

"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner ",
"rerald": "",
"siteVisitContactNo": "9004217873",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 510.00",
"flatRate": "21000",
"landOtherRate": "18000",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "483.96",
"extendOfSiteRemark": "",
"finalBuiltupArea": "561.08",
"finalCarpetArea": "510.07",
"finalSalableArea": "617.18",
"otherCarpetTotal": "0.00",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Passage + WC +
Bathroom",
"finalSaleablePercentage": "0",
"reportGeneratedDate": "Wed Mar 19 2025 10:45:16 GMT+0000 (Coordinated
Universal Time)",
"siteVisitDate": "2025-03-18"
}

```

Name	Length	Width	Total
Composition :			
Living Room	15'5"	9'9"	150.31
Passage	17'4"	2'11"	50.55

Kitchen	9'00"	6'9"	60.75
WC	6'8"	3'11"	26.11
Bedroom	9'3"	9'3"	85.56
Bedroom	10'11"	9'11"	108.26
Bathroom	3'8"	6'5"	23.53
Other Composition :			