

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bb03"
    },
    "firstName": "Sanika",
    "type": "CREDITOFFICER",
    "_id": "65b73172e1e7bf61f3d0f8c4",
    "lastName": "Apte",
    "mobileNo": "",
    "workMobileNo": "9820309326",
    "email": "1ghatkoparwestou@svcbank.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "Sanika",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d185c",
  "type": "BANK",
  "name": "SVC CO-OPERATIVE BANK LTD",
  "displayName": "SVC BANK",
  "initial": "SVC",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bb03",
  "branchCode": "000003",
  "type": "BRANCH",
  "name": "Ghatkopar (W) Branch",
  "email": "ghatkoparwestou@svcbank.com",
  "mobileNo": "02225103366",
  "alternateMobileNo": "02225103377",
  "address": "Shop No 1-3,Ground Floor,Delite Palace CHS Plot No.71/7, Shop No.1-3,
Delite Palace CHS Ltd., M G Road, Mumbai, Maharashtra 400086",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60fbaf81d8cfc56a13fa8863",
  "zoneName": "PAN INDIA"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1722582806298_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "648fcad91b499c2d52dc86f3",
  "role": "SITEENGINEER",
  "firstName": "Barkat",
  "email": "barkathodekar68@gmail.com",
  "lastName": "Hodekar",
  "mobileNo": "8879011615",
  "designation": "Site Engg",
  "shortName": "Barkat",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f9147bf3dd69653a591e8c",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Vinita",
  "email": "vinita.surve@vastukala.org",
  "lastName": "Surve",
  "mobileNo": "9820652818",
  "designation": "",
  "shortName": "V",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
},
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
```

```
    "value": "IBBI/RV/07/2018/10366",
    "label": "Registered Valuer"
  }
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
```

```
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.112643562013822",
  "longitude": "72.93468821793795"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.93468821793795,
    19.112643562013822
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "17/03/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
```

```
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Hariyali",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "11",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
```

```
"status": false,
"name": "Tehsil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shraddha Presidancey",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
```

```
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "C",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
```

```
"name": "CTS No.",
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1105",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
}
```

```
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400083",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
}
```

```
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
}
```

```
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
```

```
"max": "0.00"
},
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67d7de8001f1c07601e3a168",
"ownerName": "Ramesh Dhondu Lanjekar And Tushar Dhondu Lanjekar",
"ownerPhoneNo": "9820529162",
```

```
"appAddress": "Flat no. 1105, 11th Floor, Wing - C, Hariyali, Vikhroli East ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Allotment Letter",
      "value": "60ae1246aa6d152c1801b2e5"
    },
    "attachConfig": {
      "fromPage": 0,
      "toPage": 0
    },
    "attachInReport": false,
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/67d7de8001f1c07601e3a168/
document_1742200434716_1742200432708_allotment_letter001.pdf",
    "fileName": "document_1742200434716_1742200432708_allotment_letter001.pdf",
    "id": "719410",
    "uploadedBy": "60b7177d2ffdf65bcd65882a",
    "createdAt": "Mon Mar 17 2025 08:34:08 GMT+0000 (Coordinated Universal Time)"
  }
],
"caseNumber": "014953",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "149880",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Mar 17 2025 08:34:08 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Ramesh Dhondu Lanjekar And Tushar Dhondu Lanjekar",
    "phone": "9820529162",
    "ownershipShare": "",
    "email": "",
    "id": "378330"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
```

```
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67db91f562f551cdb6573c67",
    "name": "externallmg_1742442996618_1742442994604_image_0.jpeg",
    "path": "cases/67d7de8001f1c07601e3a168/
externallmg_1742442996618_1742442994604_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67db91f562f551cdb6573c68",
    "name": "externallmg_1742442996659_1742442994604_image_1.jpeg",
    "path": "cases/67d7de8001f1c07601e3a168/
externallmg_1742442996659_1742442994604_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67db922262f551cdb6573caa",
    "name": "externallmg_1742443038989_1742443036220_image_0.jpeg",
    "path": "cases/67d7de8001f1c07601e3a168/
externallmg_1742443038989_1742443036220_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67db922262f551cdb6573cab",
    "name": "externallmg_1742443039716_1742443036220_image_1.jpeg",
    "path": "cases/67d7de8001f1c07601e3a168/
externallmg_1742443039716_1742443036220_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67db922262f551cdb6573cac",
    "name": "externallmg_1742443040037_1742443036220_image_2.jpeg",
```

```
    "path": "cases/67d7de8001f1c07601e3a168/
externallmg_1742443040037_1742443036220_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67db922262f551cdb6573cad",
    "name": "externallmg_1742443040270_1742443036220_image_3.jpeg",
    "path": "cases/67d7de8001f1c07601e3a168/
externallmg_1742443040270_1742443036220_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67db922262f551cdb6573cae",
    "name": "externallmg_1742443040540_1742443036220_image_4.jpeg",
    "path": "cases/67d7de8001f1c07601e3a168/
externallmg_1742443040540_1742443036220_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67db922262f551cdb6573caf",
    "name": "externallmg_1742443040816_1742443036220_image_5.jpeg",
    "path": "cases/67d7de8001f1c07601e3a168/
externallmg_1742443040816_1742443036220_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67db922262f551cdb6573cb0",
    "name": "externallmg_1742443041125_1742443036220_image_6.jpeg",
    "path": "cases/67d7de8001f1c07601e3a168/
externallmg_1742443041125_1742443036220_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67db922262f551cdb6573cb1",
    "name": "externallmg_1742443041384_1742443036220_image_7.jpeg",
    "path": "cases/67d7de8001f1c07601e3a168/
externallmg_1742443041384_1742443036220_image_7.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67db922262f551cdb6573cb2",
  "name": "externallmg_1742443041646_1742443036220_image_8.jpeg",
  "path": "cases/67d7de8001f1c07601e3a168/
externallmg_1742443041646_1742443036220_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67db922262f551cdb6573cb3",
  "name": "externallmg_1742443041869_1742443036220_image_9.jpeg",
  "path": "cases/67d7de8001f1c07601e3a168/
externallmg_1742443041869_1742443036220_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67db922262f551cdb6573cb4",
  "name": "externallmg_1742443042121_1742443036220_image_10.jpeg",
  "path": "cases/67d7de8001f1c07601e3a168/
externallmg_1742443042121_1742443036220_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67db922262f551cdb6573cb5",
  "name": "externallmg_1742443042374_1742443036220_image_11.jpeg",
  "path": "cases/67d7de8001f1c07601e3a168/
externallmg_1742443042374_1742443036220_image_11.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
```

```
    "_id": "60f9147bf3dd69653a591e8c",
    "role": "MAKER + RATE VERIFIER + CHEAKER",
    "firstName": "Vinita",
    "lastName": "Surve",
    "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "67d80127700ebc688493633f",
  "note": "Pending value confirmation",
  "taskId": "67d7e6d6700ebc68849337c7",
  "createdAt": "2025-03-17T11:01:59.532Z"
},
{
  "createdBy": {
    "_id": "60f9147bf3dd69653a591e8c",
    "role": "MAKER + RATE VERIFIER + CHEAKER",
    "firstName": "Vinita",
    "lastName": "Surve",
    "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "67d8039501f1c07601e3e74e",
  "note": "Pending Visit",
  "taskId": "67d7e6d6700ebc68849337c7",
  "createdAt": "2025-03-17T11:12:21.366Z"
}
],
"createdAt": "2025-03-17T08:34:08.437Z",
"updatedAt": "2025-03-20T03:57:22.924Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 1105, 11th Floor, Wing - C, Shraddha Presidancey,
Village - Hariyali, Mumbai, 400083",
"updatedBy": "648fcad91b499c2d52dc86f3",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Ramesh Dhondu Lanjekar And Tushar Dhondu Lanjekar",
```

```
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"rerald": "",
"siteVisitContactNo": "9820529162"
```

}

Name	Length	Width	Total
Composition :			
Other			
Composition :			