

```
{
  "typeOfReport": {
    "label": "APF",
    "value": "APF"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Advance Processing Facility",
    "value": "A.P.F."
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "666d5dc4fad0e137dd90072"
    },
    "firstName": "Nikhil",
    "type": "CREDITOFFICER",
    "_id": "65f0442b857bdc098a9ba6dc",
    "lastName": "Kharat",
    "mobileNo": "",
    "workMobileNo": "9819701705",
    "email": "nikhil.kharat@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "00",
    "discussWithPerson": "Nikhil",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "666d5dc4fadc0e137dd90072",
  "name": "Administrative Office South Mumbai",
  "branchCode": "",
  "mobileNo": "0000000000",
  "alternateMobileNo": "",
  "email": "nikhil.kharat@sbi.co.in",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Mumbai Main Branch Building, Gate no 1 Horniman Circle Mumbai
samachar marg Fort."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af3d172ffdf65bcd6585cd",
```

```
"role": "PICKUPPERSON",
"firstName": "Sachin",
"email": "sachin.joshi@vastukala.org",
"lastName": "Joshi",
"mobileNo": "9167204063",
"shortName": "SJ",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af3d172ffdf65bcd6585cd\
\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "67776d60a5477d50e7dbc213",
"role": "SITEENGINEER+MAKAR+CHECKER",
"firstName": "AJAY",
"email": "ajayrewale503@gmail.com",
"lastName": "REWALE",
"mobileNo": "9766640171",
"designation": "",
"shortName": "AJAY",
"workWithDocumentMaker": "",
"profilePhoto": "users/67776d60a5477d50e7dbc213/
profilePhoto_1739252394344_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60f9147bf3dd69653a591e8c",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Vinita",
"email": "vinita.surve@vastukala.org",
"lastName": "Surve",
"mobileNo": "9820652818",
"designation": "",
"shortName": "V",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60f9147bf3dd69653a591e8c",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Vinita",
"email": "vinita.surve@vastukala.org",
"lastName": "Surve",
"mobileNo": "9820652818",
```

```
"designation": "",
"shortName": "V",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f9147bf3dd69653a591e8c",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Vinita",
  "email": "vinita.surve@vastukala.org",
  "lastName": "Surve",
  "mobileNo": "9820652818",
  "designation": "",
  "shortName": "V",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.139695664888333",
  "longitude": "72.86955844374626"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.86955844374626,
    19.139695664888333
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "18/03/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Masaj",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
```

```
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
```

```
"name": "Building Name",
"key": "buildingName",
"value": "JVLR 60",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "J V L R ",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
}
```



```
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
```

```
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
}
```

```
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Jogshwari East",
  "label": false
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
```

```
"routeLat": "",
"routeLng": "",
"stationName": "",
"routeDistance": ""
},
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```



```
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
```

```
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67d8ffa8df28417602ba7239",
"ownerName": "JVLR 60",
"ownerPhoneNo": "0000000000",
"appAddress": "C.T.S 367,367/1,to 21,Majas Village Andheri East ",
"remark": "Contact Person +91 92243 43023",
"documents": [
  {
    "documentType": {
      "label": "RERA Certificate",
      "value": "60ae129faa6d152c1801b47d"
    },
    "attachConfig": {
      "fromPage": 0,
      "toPage": 0
    },
    "attachInReport": false,
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/67d8ffa8df28417602ba7239/document_1742274458465_174227445
6826_Rajhem_Builders_and_Developers_Llp.pdf",
    "fileName": "document_1742274458465_1742274456826_Rajhem_Builders_and_D
evelopers_Llp.pdf",
    "id": "294329",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Tue Mar 18 2025 05:07:52 GMT+0000 (Coordinated Universal Time)"
  }
]
```

```
}
],
"caseNumber": "014969",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "188650",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Mar 18 2025 05:07:52 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "JVLR 60",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "484143"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67d99b7c01f1c07601e54367",
    "name": "externalImg_1742314180892_1742314177001_image_0.jpeg",
    "path": "cases/67d8ffa8df28417602ba7239/externalImg_1742314180892_1742314177001_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67d99b7c01f1c07601e54368",
    "name": "externalImg_1742314189695_1742314177001_image_1.jpeg",
    "path": "cases/67d8ffa8df28417602ba7239/externalImg_1742314189695_1742314177001_image_1.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d99b7c01f1c07601e54369",
  "name": "externallmg_1742314197529_1742314177001_image_2.jpeg",
  "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314197529_1742314177001_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d99b7c01f1c07601e5436a",
  "name": "externallmg_1742314205106_1742314177002_image_3.jpeg",
  "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314205106_1742314177002_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d99b7c01f1c07601e5436b",
  "name": "externallmg_1742314211174_1742314177002_image_4.jpeg",
  "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314211174_1742314177002_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d99b7c01f1c07601e5436c",
  "name": "externallmg_1742314216069_1742314177002_image_5.jpeg",
  "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314216069_1742314177002_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d99b7c01f1c07601e5436d",
  "name": "externallmg_1742314217794_1742314177002_image_6.jpeg",
  "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314217794_1742314177002_image_6.jpeg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d99b7c01f1c07601e5436e",
  "name": "externallmg_1742314222510_1742314177002_image_7.jpeg",
  "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314222510_1742314177002_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d99b7c01f1c07601e5436f",
  "name": "externallmg_1742314233294_1742314177002_image_8.jpeg",
  "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314233294_1742314177002_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d99b7c01f1c07601e54370",
  "name": "externallmg_1742314254450_1742314177002_image_9.jpeg",
  "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314254450_1742314177002_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d99b7c01f1c07601e54371",
  "name": "externallmg_1742314271822_1742314177002_image_10.jpeg",
  "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314271822_1742314177002_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d99b7c01f1c07601e54372",
  "name": "externallmg_1742314288817_1742314177002_image_11.jpeg",
  "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314288817_1742314177002_image_11.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d99b7c01f1c07601e54373",
  "name": "externallmg_1742314302652_1742314177002_image_12.jpeg",
  "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314302652_1742314177002_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d99b7c01f1c07601e54374",
  "name": "externallmg_1742314315228_1742314177002_image_13.jpeg",
  "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314315228_1742314177002_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d99b7c01f1c07601e54375",
  "name": "externallmg_1742314326387_1742314177002_image_14.jpeg",
  "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314326387_1742314177002_image_14.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d99b7c01f1c07601e54376",
  "name": "externallmg_1742314331810_1742314177002_image_15.jpeg",
  "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314331810_1742314177002_image_15.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67d99b7c01f1c07601e54377",
  "name": "externallmg_1742314342517_1742314177002_image_16.jpeg",
  "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314342517_1742314177002_image_16.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67d99b7c01f1c07601e54378",
    "name": "externallmg_1742314353896_1742314177002_image_17.jpeg",
    "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314353896_1742314177002_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67d99b7c01f1c07601e54379",
    "name": "externallmg_1742314356166_1742314177002_image_18.jpeg",
    "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314356166_1742314177002_image_18.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67d99b7c01f1c07601e5437a",
    "name": "externallmg_1742314358511_1742314177002_image_19.jpeg",
    "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314358511_1742314177002_image_19.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d99bfbdf28417602bb3181",
    "name": "externallmg_1742314333146_1742314241741_image_0.jpeg",
    "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314333146_1742314241741_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d99bfbdf28417602bb3182",
    "name": "externallmg_1742314356206_1742314241741_image_1.jpeg",
    "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314356206_1742314241741_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "67d99bfddf28417602bb3183",
    "name": "externallmg_1742314366856_1742314241741_image_2.jpeg",
    "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314366856_1742314241741_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d99bfddf28417602bb3184",
    "name": "externallmg_1742314372576_1742314241741_image_3.jpeg",
    "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314372576_1742314241741_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d99bfddf28417602bb3185",
    "name": "externallmg_1742314381597_1742314241741_image_4.jpeg",
    "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314381597_1742314241741_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d99bfddf28417602bb3186",
    "name": "externallmg_1742314391947_1742314241741_image_5.jpeg",
    "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314391947_1742314241741_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d99bfddf28417602bb3187",
    "name": "externallmg_1742314393796_1742314241741_image_6.jpeg",
    "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314393796_1742314241741_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```



```
    "_id": "67d99bfddf28417602bb3188",
    "name": "externalimg_1742314406068_1742314241741_image_7.jpeg",
    "path": "cases/67d8ffa8df28417602ba7239/
externalimg_1742314406068_1742314241741_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d99bfddf28417602bb3189",
    "name": "externalimg_1742314412266_1742314241741_image_8.jpeg",
    "path": "cases/67d8ffa8df28417602ba7239/
externalimg_1742314412266_1742314241741_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d99bfddf28417602bb318a",
    "name": "externalimg_1742314419466_1742314241741_image_9.jpeg",
    "path": "cases/67d8ffa8df28417602ba7239/
externalimg_1742314419466_1742314241741_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d99bfddf28417602bb318b",
    "name": "externalimg_1742314428596_1742314241741_image_10.jpeg",
    "path": "cases/67d8ffa8df28417602ba7239/
externalimg_1742314428596_1742314241741_image_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d99bfddf28417602bb318c",
    "name": "externalimg_1742314434491_1742314241741_image_11.jpeg",
    "path": "cases/67d8ffa8df28417602ba7239/
externalimg_1742314434491_1742314241741_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d99bfddf28417602bb318d",
```

```
    "name": "externallmg_1742314441521_1742314241741_image_12.jpeg",
    "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314441521_1742314241741_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d99bfbd28417602bb318e",
    "name": "externallmg_1742314451938_1742314241741_image_13.jpeg",
    "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314451938_1742314241741_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d99bfbd28417602bb318f",
    "name": "externallmg_1742314453676_1742314241742_image_14.jpeg",
    "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314453676_1742314241742_image_14.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d99bfbd28417602bb3190",
    "name": "externallmg_1742314456936_1742314241742_image_15.jpeg",
    "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314456936_1742314241742_image_15.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d99bfbd28417602bb3191",
    "name": "externallmg_1742314460161_1742314241742_image_16.jpeg",
    "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314460161_1742314241742_image_16.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d99bfbd28417602bb3192",
    "name": "externallmg_1742314476377_1742314241742_image_17.jpeg",
```

```
    "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314476377_1742314241742_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d99bfbdf28417602bb3193",
    "name": "externallmg_1742314481926_1742314241742_image_18.jpeg",
    "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314481926_1742314241742_image_18.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d99d1d700ebc6884947330",
    "name": "externallmg_1742314580879_1742314569702_image_0.jpeg",
    "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314580879_1742314569702_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d99d1d700ebc6884947331",
    "name": "externallmg_1742314598860_1742314569702_image_1.jpeg",
    "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314598860_1742314569702_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d99d1d700ebc6884947332",
    "name": "externallmg_1742314604737_1742314569702_image_2.jpeg",
    "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314604737_1742314569702_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d99d1d700ebc6884947333",
    "name": "externallmg_1742314618313_1742314569702_image_3.jpeg",
    "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314618313_1742314569702_image_3.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d99d1d700ebc6884947334",
  "name": "externallmg_1742314667815_1742314569702_image_4.jpeg",
  "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314667815_1742314569702_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d99d1d700ebc6884947335",
  "name": "externallmg_1742314682528_1742314569702_image_5.jpeg",
  "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314682528_1742314569702_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d99d1d700ebc6884947336",
  "name": "externallmg_1742314707374_1742314569702_image_6.jpeg",
  "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314707374_1742314569702_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d99d1d700ebc6884947337",
  "name": "externallmg_1742314732580_1742314569702_image_7.jpeg",
  "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314732580_1742314569702_image_7.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d99d1d700ebc6884947338",
  "name": "externallmg_1742314752840_1742314569702_image_8.jpeg",
  "path": "cases/67d8ffa8df28417602ba7239/
externallmg_1742314752840_1742314569702_image_8.jpeg",
  "orientation": "landscape"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67d99d1d700ebc6884947339",
      "name": "externalImg_1742314762034_1742314569702_image_9.jpeg",
      "path": "cases/67d8ffa8df28417602ba7239/
externalImg_1742314762034_1742314569702_image_9.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67d99d1d700ebc688494733a",
      "name": "externalImg_1742314763605_1742314569702_image_10.jpeg",
      "path": "cases/67d8ffa8df28417602ba7239/
externalImg_1742314763605_1742314569702_image_10.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67d99d1d700ebc688494733b",
      "name": "externalImg_1742314764369_1742314569702_image_11.jpeg",
      "path": "cases/67d8ffa8df28417602ba7239/
externalImg_1742314764369_1742314569702_image_11.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67d99d1d700ebc688494733c",
      "name": "externalImg_1742314765792_1742314569702_image_12.jpeg",
      "path": "cases/67d8ffa8df28417602ba7239/
externalImg_1742314765792_1742314569702_image_12.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalDocuments": [],
  "processingDocuments": [],
  "leadRemarks": [],
  "audioRemarks": [],
  "remarks": [],
  "createdAt": "2025-03-18T05:07:53.012Z",
  "updatedAt": "2025-03-18T16:19:41.682Z",
  "__v": 0,
```

```

"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential APF No. Ground Floor, JVLR 60, J V L R , Village - Masaj,
Jogshwari East, Mumbai",
"updatedBy": "67776d60a5477d50e7dbc213",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "JVLR 60",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"reald": "",
"siteVisitContactNo": "0000000000"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			