## VALUATION REPORT (IN RESPECT OF FLAT)

|     | General   |  |   |  |  |  |
|-----|---|--|---|--|--|--|
| 1   | Purpose for which the valuation is made   |  | : | To assess Fair Market Value of the property for Banking Purpose Purpose.   |  |  |
| 2   | a)  | Date of inspection   | : | 28.01.2025   |  |  |
|     | b)  | Date of which the valuation is made                        | : | 31.01.2025   |  |  |
| 3   | List of documents produced for perusal:  I) Copy of Allotment Letter Dated 06.01.2025 between Mr. Ravindra Shivaji Saidane(The Owner) And Mr. Laxman Gangurde(The purchaser).  II) Copy of Title Report Dated 08.01.2025.  III) Copy of Previous Valuation Report Dated 15.03.2023. |  |   |  |  |  |
| 4   | ,   |  |   | Name of Owner: Mr. Ravindra Shivaji Saidane through Reliance Commercial Finance Ltd. (Presently Autham Investment & Infrastructure Ltd.)  Name of Proposed Purchaser: Mr. Laxman Gangurde  Residential Flat No. B-6, Stilt Floor, Wing - B, "Kulswamini Heights", Near Water Tank, Plot No. 62+63+64, Datta Nagar, Village - Chunchale Shiwar, Gut No. 52+4A/2/1+2+4+5+6/A, Taluka - Nashik, District - Nashik, Nashik, 422010, State - Maharashtra, India.  Contact Person: Mr. Ravindra Shivaji Saidane through Reliance Commercial Finance Ltd. (Presently Autham Investment & Infrastructure Ltd.) (Owner) Mobile No. 9881881799 |  |  |
| 5   |   | escription of the property (Including old / freehold etc.) | : | sole ownership  The property is a Residential Flat located on Stilt Floor. The composition of Residential Flat is 1 Bedroom + Living Room + Kitchen + Balcony + Bathroom + WC + Passage. (1 BHK The property is at 15.5 KM distance from Nashik Road Railway Station.  |  |  |
| 5a. | Total Le  | ease Period & remaining period (if old)                    | : |  |  |  |
| 6   | Locatio   | n of property  |   |  |  |  |
| a)  | Plot No   | . / Survey No.   | : | Plot No - 62+63+64   |  |  |
| b)  | Door N  | 0.   | : | Residential Flat No. B-6   |  |  |
| c)  | C.T.S.  | No. / Village  | : | Village - Chunchale Shiwar   |  |  |
| d)  | Ward /  | Taluka   | : | Taluka - Nashik  |  |  |
| e)  | Mandal  | / District   | : | District - Nashik  |  |  |

| f)   | Date of issue and validity of layout of approved map / plan   | : | Copy of Approved Building Plan Not Provided & Not Verified   |                                     |  |
|------|---|---|--|-------------------------------------|--|
| g)   | Approved map / plan issuing authority   | : |  |                                     |  |
| h)   | Whether genuineness or authenticity of approved map/ plan is verified   | : | No   |                                     |  |
| i)   | Any other comments by our empanelled valuers on authentic of approved plan  | : | Yes  |                                     |  |
| 7    | Postal address of the property  | : | Residential Flat No. B-6, Stilt Floor, Wing - B, <b>"Kulswamini Heights"</b> , Near Water Tank, Plot No. 62+63+64, Datta Nagar, Village - Chunchale Shiwar, Gut No. 52+4A/2/1+2+4+5+6/A, Taluka - Nashik, District - Nashik, Nashik, 422010, State - Maharashtra, India. |                                     |  |
| 8    | City / Town   |   | City - Nashik  |                                     |  |
|      | Residential area  | : | Yes  |                                     |  |
|      | Commercial area   | : | No   |                                     |  |
|      | Industrial area   | : | No   |                                     |  |
| 9    | Classification of the area  |   |  |                                     |  |
|      | i) High / Middle / Poor   |   | Middle Class   |                                     |  |
|      | ii) Urban / Semi Urban / Rura   |   | Urban  |                                     |  |
| 10   | Coming under Corporation limit / Village Panchayat / Municipality   | : | Village - Chunchale Shiwar<br>Nashik Municipal Corporation   |                                     |  |
| 11   | Whether covered under any State / Central Govt. enactments (e.g., Urban Land Ceiling Act) or notified under agency area/ scheduled area / cantonment area | : | No   |                                     |  |
| 12   | Boundaries of the property  | : | As per site  | As per Document                     |  |
|      | North   | : | Building   | Plot No. 61                         |  |
|      | South   | : | A Wing   | Open Space                          |  |
|      | East  | : | Road 6 Mtrs. Colony Road   |                                     |  |
|      | West  | : | Open Plot Adj. Gat No. 53  |                                     |  |
| 13   | Dimensions of the site  |   | N. A. as property under consideration is a Residential Flat in a building.   |                                     |  |
|      |   | : | As per the Deed As per Actuals   |                                     |  |
|      | North   | : | Side Marginal space Side Marginal space  |                                     |  |
|      | South   | : | Flat No. B-5 in B wing   | Flat No. B-5 in B wing              |  |
|      | East  | : | Flat No. B- 3 in B wing  | Staircase & Flat No. B- 3 in B wing |  |
|      | West  | : | Side Marginal Space  | Side Marginal Space                 |  |
| 13.2 | Latitude, Longitude & Co-ordinates of Flat  | : | 19°57'36.9"N 73°43'38.8"E  |                                     |  |

| Heights", Near Water Tank, Plot No. 62+63+64, Da<br>Nagar, Village - Chunchale Shiwar, Gut N   | 14  | Extent of the site                          | : | Carpet Area in Sq. Ft. = 444.30 (Area as per Site measurement)  |
|--|-----|---|---|---|
| (Area As Per Title Report)  (Area As Per Title Person  (Area A |     |   |   |   |
| occupied by tenant since how long? Rent received per month.  II APARTMENT BUILDING  1. Nature of the Apartment : Residential  2. Location : C.T.S. No. : Block No. : -  Ward No. : -  Village / Municipality / Corporation : Village - Chunchale Shiwar, Nashik Municipal Corporation : Residential Flat No. B-6, Stilt Floor, Wing - B, "Kulswam Heights", Near Water Tank, Plot No. 62+63+64, Da Nagar, Village - Chunchale Shiwar, Gut N Sz+44/2/12-44-5-6/A, Taluka - Nashik, District - Nash Nashik, 422010, State - Maharashtra, India  3. Description of the locality Residential / Residential Commercial / Mixed : Residential Commercial / Mixed : Residential Commercial / Mixed : Residential Stilt + 3 Upper Floors : Rec. C. Framed Structure : Normal : Good : Northide : | 15  | Extent of the site considered for Valuation | : |   |
| 1. Nature of the Apartment : Residential : C.T.S. No. : Discrete of the Apartment : Residential : C.T.S. No. : Discrete of Road (Pin Code) : - Village - Chunchale Shiwar, Nashik Municipal Corporation : - Village - Chunchale Shiwar, Nashik Municipal Corporation : - Village - Chunchale Shiwar, Nashik Municipal Corporation : Residential Flat No. B-6, Stilt Floor, Wing - B, "Kutswam Heights", Near Water Tank, Plot No. 62+63+64, Da Nagar, Village - Chunchale Shiwar, Gut N 52+4A/21+2+4-5+6/A, Taluka - Nashik, District - Nash Nashik, 422010, State - Maharashtra, India : Residential / Commercial / Mixed : Residential / Commercial / Mixed : Residential / Commercial / Mixed : 2013 (As per site information) : Stilt + 3 Upper Floors : Stilt + 3 Upper Floors : Stilt + 3 Upper Floors : R.C.C. Framed Structure : R.C.C. Framed Structure : Number of Dwelling units in the building : Stilt Floor is having 4 Flats : Normal : Normal : Normal : Normal : Good : Normal : Normal : Good : Caparaman  | 16  | occupied by tenant since how long? Rent     | : | Vacant  |
| 2. Location  C.T.S. No.  Block No.  Ward No.  Village / Municipality / Corporation  Door No., Street or Road (Pin Code)  Door No., Street or Road (Pin Code)  Door No., Street or Road (Pin Code)  Bescription of the locality Residential / Commercial / Mixed  4. Year of Construction  Substitution  Number of Floors  Type of Structure  Number of Dwelling units in the building  Quality of Construction  Residential  Stilt Floor is having 4 Flats  Quality of Construction  Appearance of the Building  Appearance of the Building  Maintenance of the Building  Lift  Protected Water Supply  Underground Sewerage  Car parking - Open / Covered  Is compound wall existing?  Yes  Is pavement laid around the Building  Yes  Yes  Yes  Yes  Is pavement laid around the Building  Yes  Yes  | II  | APARTMENT BUILDING                          |   |   |
| C.T.S. No.  Block No.  Ward No.  Village / Municipality / Corporation  Door No., Street or Road (Pin Code)  Besciential Flat No. B-6, Stilt Floor, Wing - B, "Kulswam Heights". Near Water Tank, Plot No. 62+63+64, Da Nagar, Village - Chunchale Shiwar, Gut Nagar, Village - Chunchale Shiwar, Gu | 1.  | Nature of the Apartment                     | : | Residential   |
| Block No.  Ward No.  Village / Municipality / Corporation  Village - Chunchale Shiwar, Nashik Municipal Corporation  Door No., Street or Road (Pin Code)  Boor No., Street or Road (Pin Code)  Boor No., Street or Road (Pin Code)  Residential Flat No. B-6, Stilt Floor, Wing - B, "Kulswam Heights", Near Water Tank, Plot No. 62+63+64, Da Nagar, Village - Chunchale Shiwar, Gut Nashik, 422010, State - Maharashtra, India  Bescription of the locality Residential / Commercial / Mixed  Residential  Reside | 2.  | Location                                    |   |   |
| Ward No.  Village / Municipality / Corporation  Village - Chunchale Shiwar, Nashik Municipal Corporation  Door No., Street or Road (Pin Code)  Personal Residential Flat No. B-6, Stilt Floor, Wing - B, "Kulswam Heights", Near Water Tank, Plot No. 62+63+64, Da Nagar, Village - Chunchale Shiwar, Gut Nagar, Village - Chunchale Shiwa |     | C.T.S. No.                                  | : |   |
| Village / Municipality / Corporation  Village - Chunchale Shiwar, Nashik Municipal Corporation  Door No., Street or Road (Pin Code)  Passidential Flat No. B-6, Stilt Floor, Wing - B, "Kulswam Heights", Near Water Tank, Plot No. 62+63+64, Da Nagar, Village - Chunchale Shiwar, Gut N 52+4A/2/1+2+4+5+6/A, Taluka - Nashik, District - Nash Nashik, 422010, State - Maharashtra, India  Description of the locality Residential / Commercial / Mixed  4. Year of Construction  Stilt + 3 Upper Floors  Type of Structure  Number of Dwelling units in the building  Rec.C. Framed Structure  Number of Dwelling units in the building  Rec.C. Framed Structure  Normal  Appearance of the Building  Good  Maintenance of the Building  Cood  The Facilities Available  Lift  Not Provided  Protected Water Supply  Underground Sewerage  Car parking - Open / Covered  Is Compound wall existing?  Is pavement laid around the Building  Yes   |     | Block No.                                   | : | -   |
| Nashik Municipal Corporation  Door No., Street or Road (Pin Code)  : Residential Flat No. B-6, Stilt Floor, Wing - B, "Kulswam Heights", Near Water Tank, Plot No. 62+63+64, Da Nagar, Village - Chunchale Shiwar, Gut N 52+4A/2/1+2+4+5+6/A, Taluka - Nashik, District - Nash Nashik, 422010, State - Maharashtra, India  3. Description of the locality Residential / Commercial / Mixed  4. Year of Construction  5. Number of Floors  6. Type of Structure  7. Number of Dwelling units in the building  8. Quality of Construction  9. Appearance of the Building  10. Maintenance of the Building  11. Facilities Available  Lift  Protected Water Supply  Underground Sewerage  Car parking - Open / Covered  Is Compound wall existing?  Is pavement laid around the Building  2. Residential Flat No. B-6, Stilt Floor, Wing - B, "Kulswam Heights", Dea Nagar, Village - Chunchale Shiwar, Gut Nagar, Village - Chunchale Shiwar, Gut Nashik, 422010, State - Mashik, District - Nash Nashik, District - Nash Nashik, District - Nash Nashik, 422010, State - Mashik, District - Nash Nashik, 22010, State - Mashik, District - Nash Nashik, 422010, State - Mashik, District - Nash Nashik, 422010, State - Mashik, District - Nash Nashik, 22010, State - Mashik, District - Nash Nashik, 22010, State - Mashik, 22010, State - Mashik, District - Nash Nashik, 22010, State - Mashik, 22010, State - M |     | Ward No.                                    | : | -   |
| Heights", Near Water Tank, Plot No. 62+63+64, Da Nagar, Village - Chunchale Shiwar, Gut N 52+4A/2/1+2+4+5+6/A, Taluka - Nashik, District - Nash Nashik, 422010, State - Maharashtra, India  3. Description of the locality Residential / Commercial / Mixed  4. Year of Construction  5. Number of Floors  6. Type of Structure  7. Number of Dwelling units in the building  8. Quality of Construction  9. Appearance of the Building  10. Maintenance of the Building  11. Facilities Available  12. Lift  13. Not Provided  14. Protected Water Supply  15. Underground Sewerage  16. Car parking - Open / Covered  17. Sumpound wall existing?  18. Compound wall existing?  19. Sexience Tank, Plot No. 62+63+64, Da Nagar, Club In Nashik, Alex In Nashik, Alex In Nashik, Alex In India In Nashik, Alex In India In Nashik, Alex India I |     | Village / Municipality / Corporation        |   | ·   |
| Commercial / Mixed  4. Year of Construction : 2013 (As per site information)  5. Number of Floors : Stilt + 3 Upper Floors  6. Type of Structure : R.C.C. Framed Structure  7. Number of Dwelling units in the building : Stilt Floor is having 4 Flats  8. Quality of Construction : Normal  9. Appearance of the Building : Good  10. Maintenance of the Building : Good  11. Facilities Available : Not Provided  Protected Water Supply : Municipal Water Supply  Underground Sewerage : Connected to Municipal Sewerage System  Car parking - Open / Covered : Covered Car Parking  Is Compound wall existing? : Yes  Is pavement laid around the Building : Yes  |     | Door No., Street or Road (Pin Code)         |   | Residential Flat No. B-6, Stilt Floor, Wing - B, <b>"Kulswamini Heights"</b> , Near Water Tank, Plot No. 62+63+64, Datta Nagar, Village - Chunchale Shiwar, Gut No. 52+4A/2/1+2+4+5+6/A, Taluka - Nashik, District - Nashik, Nashik, 422010, State - Maharashtra, India |
| 5. Number of Floors : Stilt + 3 Upper Floors 6. Type of Structure : R.C.C. Framed Structure 7. Number of Dwelling units in the building : Stilt Floor is having 4 Flats 8. Quality of Construction : Normal 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available  Lift : Not Provided  Protected Water Supply : Municipal Water Supply  Underground Sewerage : Connected to Municipal Sewerage System  Car parking - Open / Covered : Covered Car Parking  Is Compound wall existing? : Yes  Is pavement laid around the Building : Yes  | 3.  |   | : | Residential   |
| 6. Type of Structure : R.C.C. Framed Structure  7. Number of Dwelling units in the building : Stilt Floor is having 4 Flats  8. Quality of Construction : Normal  9. Appearance of the Building : Good  10. Maintenance of the Building : Good  11. Facilities Available : Not Provided  Lift : Not Provided  Protected Water Supply : Municipal Water Supply  Underground Sewerage : Connected to Municipal Sewerage System  Car parking - Open / Covered : Covered Car Parking  Is Compound wall existing? : Yes  Is pavement laid around the Building : Yes   | 4.  | Year of Construction                        | : | 2013 (As per site information)  |
| 7. Number of Dwelling units in the building : Stilt Floor is having 4 Flats  8. Quality of Construction : Normal  9. Appearance of the Building : Good  10. Maintenance of the Building : Good  11. Facilities Available : Not Provided  Protected Water Supply : Municipal Water Supply  Underground Sewerage : Connected to Municipal Sewerage System  Car parking - Open / Covered : Covered Car Parking  Is Compound wall existing? : Yes  Is pavement laid around the Building : Yes  | 5.  | Number of Floors                            | : | Stilt + 3 Upper Floors  |
| 8. Quality of Construction : Normal : Good : International : International : Hot Provided : Not Provided : Municipal Water Supply : Municipal Water Supply : Underground Sewerage : Connected to Municipal Sewerage System : Car parking - Open / Covered : Covered Car Parking : Yes : Is pavement laid around the Building : Yes   | 6.  | Type of Structure                           | : | R.C.C. Framed Structure   |
| 9. Appearance of the Building : Good  10. Maintenance of the Building : Good  11. Facilities Available : Not Provided  Protected Water Supply : Municipal Water Supply  Underground Sewerage : Connected to Municipal Sewerage System  Car parking - Open / Covered : Covered Car Parking  Is Compound wall existing? : Yes  Is pavement laid around the Building : Yes  | 7.  | Number of Dwelling units in the building    | : | Stilt Floor is having 4 Flats   |
| 10. Maintenance of the Building : Good  11. Facilities Available : Not Provided  Lift : Not Provided : Municipal Water Supply  Underground Sewerage : Connected to Municipal Sewerage System  Car parking - Open / Covered : Covered Car Parking  Is Compound wall existing? : Yes  Is pavement laid around the Building : Yes   | 8.  | Quality of Construction                     | : | Normal  |
| 11. Facilities Available  Lift : Not Provided  Protected Water Supply : Municipal Water Supply  Underground Sewerage : Connected to Municipal Sewerage System  Car parking - Open / Covered : Covered Car Parking  Is Compound wall existing? : Yes  Is pavement laid around the Building : Yes  | 9.  | Appearance of the Building                  | : | Good  |
| Lift : Not Provided  Protected Water Supply : Municipal Water Supply  Underground Sewerage : Connected to Municipal Sewerage System  Car parking - Open / Covered : Covered Car Parking  Is Compound wall existing? : Yes  Is pavement laid around the Building : Yes  | 10. | Maintenance of the Building                 | : | Good  |
| Protected Water Supply  Underground Sewerage  Car parking - Open / Covered  Is Compound wall existing?  Is pavement laid around the Building  Municipal Water Supply  Connected to Municipal Sewerage System  Covered Car Parking  Yes   | 11. | Facilities Available                        |   |   |
| Underground Sewerage : Connected to Municipal Sewerage System  Car parking - Open / Covered : Covered Car Parking  Is Compound wall existing? : Yes  Is pavement laid around the Building : Yes  |     | Lift  | : | Not Provided  |
| Car parking - Open / Covered : Covered Car Parking  Is Compound wall existing? : Yes  Is pavement laid around the Building : Yes   |     | Protected Water Supply                      | : | Municipal Water Supply  |
| Is Compound wall existing? : Yes Is pavement laid around the Building : Yes  |     | Underground Sewerage                        | : | Connected to Municipal Sewerage System  |
| Is pavement laid around the Building : Yes   |     | Car parking - Open / Covered                | : | Covered Car Parking   |
|  |     | Is Compound wall existing?                  | : | Yes   |
| III Residential Flat   |     | Is pavement laid around the Building        | : | Yes   |
|  | III | Residential Flat                            |   |   |

| 1.  | The floor in which the Flat is situated                     | : | Stilt Floor  |
|-----|---|---|--|
| 2.  | Door No. of the Flat  | : | Residential Flat No. B-6   |
| 3.  | Specifications of the Flat                                  |   |  |
|     | Roof  | : | R. C. C. Slab  |
|     | Flooring  | : | Vitrified Tile Flooring  |
|     | Doors   | : | Teak Wood / Glass Door   |
|     | Windows   | : | Wooden frame openable widow with M. S. Grill   |
|     | Fittings  |   | Concealed plumbing with C.P. fittings. Casing Capping Electrical wiring  |
|     | Finishing   | : | Cement Plastering  |
| 4.  | House Tax   |   |  |
|     | Assessment No.  | : | Details Not Provided   |
|     | Tax paid in the name of                                     | : | Details Not Provided   |
|     | Tax amount  | : | Details Not Provided   |
| 5.  | Electricity Service connection No.                          |   | Details Not Provided   |
|     | Meter Card is in the name of                                | : | Details Not Provided   |
| 6.  | How is the maintenance of the Flat?                         |   | Average  |
| 7.  | Sale Deed executed in the name of                           |   | Name of Owner: Mr. Ravindra Shivaji Saidane through Reliance Commercial Finance Ltd. (Presently Autham Investment & Infrastructure Ltd.) Name of Proposed Purchaser: Mr. Laxman Gangurde |
| 8.  | What is the undivided area of land as per Sale Deed?        | : | NA   |
| 9.  | What is the plinth area of the Flat?                        | : | Built Up Area in Sq. Ft. = 554.00<br>(Area as per Title Report)  |
| 10. | What is the floor space index (app.)                        | : | As per NMC Norms   |
| 11. | What is the Carpet area of the Flat?                        | : | Carpet Area in Sq. Ft. = 444.30 (Area As per actual site measurement)  |
| 12. | Is it Posh / I Class / Medium / Ordinary?                   | : | Medium   |
| 13. | Is it being used for Residential or Commercial purpose?     | : | Residential Purpose  |
| 14. | Is it Owner-occupied or let out?                            | : | Vacant   |
| 15. | If rented, what is the monthly rent?                        | : | ₹ 3600/-   |
| IV  | MARKETABILITY   |   |  |
| 1.  | How is the marketability?                                   | : | Average  |
| 2.  | What are the factors favoring for an extra Potential Value? | : | Located inn developed area   |

| 3. | Any negative factors are observed which affect the market value in general?  | :     | NA  |
|----|--|-------|---|
| ٧  | Rate   |       |   |
| 1. | After analyzing the comparable sale instances, what is the composite rate for a similar Flat with same specifications in the adjoining locality? - (Along with details / reference of at - least two latest deals / transactions with respect to adjacent properties in the areas) | • •   | ₹ 3814/- to ₹ 4820/- per Sq. Ft. on Carpet Area<br>₹ 3178/- to ₹ 4017/- per Sq. Ft. on Built Up Area  |
| 2. | Assuming it is a new construction, what is the adopted basic composite rate of the Flat under valuation after comparing with the specifications and other factors with the Flat under comparison (give details).   | ••    | ₹ 3,500/- per Sq. Ft.   |
| 3. | Break – up for the rate  | :     |   |
|    | I. Building + Services   | :     | ₹ 2,000/- per Sq. Ft.   |
|    | II. Land + others  | :     | ₹ 1,500/- per Sq. Ft.   |
| 4. | Guideline rate obtained from the Registrar's Office for new property (an evidence thereof to be enclosed)  | ./ // | ₹ 28,600/- per Sq. M.<br>i.e. ₹ 2,657/- per Sq. Ft.   |
|    | Guideline rate(an evidence thereof to be enclosed)   |       | ₹ 25,696/- per Sq. M.<br>i.e. ₹ 2,387/- per Sq. Ft.   |
| 5. | Registered Value(if available)   | -/-   | N.A.  |
| VI | COMPOSITE RATE ADOPTED AFTER DEPRECIATION  |       |   |
| а  | Depreciated building rate  |       |   |
|    | Replacement cost of Flat with Services (v(3)i)   | • •   | ₹ 2,000/- per Sq. Ft.   |
|    | Age of the building  |       | 12 years  |
|    | Life of the building estimated   | • •   | 48 years Subject to proper, preventive periodic maintenance & structural repairs.   |
|    | Depreciation percentage assuming the salvage value as 10%  | :     | 18.00%  |
|    | Depreciation Ratio of the building   |       | -   |
| b  | Total composite rate arrived for Valuation   |       |   |
|    | Depreciated building rate VI (a)   | :     | ₹ 1,640/- per Sq. Ft.   |
|    | Rate for Land & other V (3) ii   | :     | ₹ 1,500/- per Sq. Ft.   |
|    | Total Composite Rate   | :     | ₹ 3,140/- per Sq. Ft.   |
|    | Remarks  | :     | 1. Our Report is Based On Documents Provided By Bank i.e. A) TSR B) Previous Valuation Report C) Allotment Letter. 2. Title report regarding the same shall be advisable. |

| No. | Description                                      | Qty.           | Rate per unit (₹) | Estimated Value (₹) |
|-----|--|----------------|-------------------|---------------------|
| 1   | Present value of the Flat                        | 554.00 Sq. Ft. | 3,140.00          | 17,39,560.00        |
| 2   | Wardrobes  |                |                   |                     |
| 3   | Showcases  |                |                   |                     |
| 4   | Kitchen arrangements                             |                |                   |                     |
| 5   | Superfine finish                                 |                |                   |                     |
| 6   | Interior Decorations                             |                |                   |                     |
| 7   | Electricity deposits / electrical fittings, etc. |                |                   |                     |
| 8   | Extra collapsible gates / grill works, etc.      |                |                   |                     |
| 9   | Potential value, if any                          |                |                   |                     |
| 10  | Others / Car Parking                             |                |                   |                     |
|     | Total value of the property                      | 17,39,560.00   |                   |                     |
|     | Realizable value of the property                 | 15,65,604.00   |                   |                     |
|     | Distress value of the property                   | 13,91,648.00   |                   |                     |
|     | Insurable value of the property (554.00 X 2,0    | 11,08,000.00   |                   |                     |
|     | Guideline value of the property (554.00 X 2,3    | ¥              | 13,22,398.00      |                     |