Valuation Report of the Immovable Property



Details of the property under consideration:

Name of Owner : Mr. Amit Kumar & Mrs. Nisha Shersingh Adhikari

Flat No. 1204, Basement Floor, Building No 7, Wing D, **"Agarwal Exotica Coop. Hsg. Soc. Ltd."**, Yashwant Smart City, Sector/Area. 1, Village - Gokhivare, Taluka - Vasai , District - Palghar, Vasai (East), 401 208, State - Maharashtra, India.

Latitude Longitude : 19°23'41.7"N 72°50'58.9"E

Think. Valuation Done for: reate

State Bank of India RASMECCC Bhayandar Venkatesh Orchid, 150 Feet Road, Near Flyover, Bhayander (West), District Thane, State - Maharashtra, Country - India

Vastukala Consultants India Pvt. Ltd.

Mumbai · Delhi NCR · Aurangabad · Nanded · Indore · Pune · Raipur · Jaipur · Ahmedabad · Rajkot · Thane · Nashik

www.vastukala.org





Valuation Report Prepared For: SBIRASMECCC Bhayandar/ Mr. Amit Kumar & Mrs. Nisha Shersingh Adhikari (000459/000336) V

36) Page 2 of 24 Vastu/Mumbai/12/2022/000336 03/0-0-SBSH Date: 03.12.2022

VALUATION OPINION REPORT

The property bearing Flat No. 1204, Basement Floor, Building No 7, Wing D, **"Agarwal Exotica Co-op. Hsg. Soc. Ltd."**, Yashwant Smart City, Sector/Area. 1, Village - Gokhivare, Taluka - Vasai , District - Palghar, Vasai (East), 401 208, State - Maharashtra, India. belongs to **Mr. Amit Kumar & Mrs. Nisha Shersingh Adhikari**

Boundaries of the property						
North	:	open plot				
South	:	Dosti pine				
East	:	Dosti Cedar				
West	:	Open plot				

Considering various parameters recorded, existing economic scenario, and the information that is available with reference to the development of neighbourhood and method selected for valuation, we are of the opinion that, the property premises can be assessed and **Fair Market Value** for this particular purpose at ₹ 45,25,500.00 (Rupees Forty Five Lakh Twenty Five Thousand Five Hundred Only Only).

The valuation of the property is based on the documents produced by the concern. Legal aspects have not been taken into considerations while preparing this report.

Hence certified

For VASTUKALA CONSULTANTS (I) PVT. LTD.

C.M.D.

Director



Manoj Chalikwar

Think.Innovate.Create

Govt. Reg. Valuer Chartered Engineer (India) Reg. No. IBBI/RV/07/2018/10366 SBI Empanelment No.: SME/TCC/2021-22/86/3 Encl.: Valuation report



 Our Pan India Presence at :

 Mumbai
 P Aurangabad
 Pune
 Pune
 Pan
 Pan

 Regd. Office : 121, 1st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai - 400 093, (M.S.), INDIA
 TeleFax : +91 22 28371325/24

[✓] mumbai@vastukala.org

Vastukala Consultants India Pvt. Ltd.

121, 1 st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai - 400 093

To, **The Branch Manager, State Bank of India RASMECCC Bhayandar** Venkatesh Orchid, 150 Feet Road, Near Flyover, Bhayander (West), District Thane, State - Maharashtra, Country - India

VALUATION REPORT (IN RESPECT OF FLAT)

				General
1	Purpos	e for which the valuation is made	:	To assess Fair Market Value of the property for Bank Loan Purpose.
2	a)	Date of inspection	:	01.01.1970
	b)	Date of which the valuation is made	:	03.12.2022
3	List of (I) II) III) IV) V)	Agarwal Realtors Allottee - Mr. Amit Kum Copy of Occupancy Certificate - Dated 2 & 0509 / 66 / 2020-21 issued by Vasai V Copy of RERA Certificate - Dated 09/09/2 Maharashtra Real Estate Regulatory Aut Copy of Commencement Certificate - Da VP-329, 0815 & 0509 / 0196 / 2017-20 is	har 8 4/12 irar 2021 hori ted ssue	2/2020 having Document No.VVCMC / TP / OC / VP-329, 0815 City Municipal Corporation having Document No.P99000002405 issued by
4	Name (es) wit	of the owner(s) and his / their address th Phone no. (details of share of each in case of joint ownership)	y Mu	
5		escription of the property (Including old / freehold etc.)	:	The property is a Residential Flat located on Basement Floor The composition of Residential Flat is 1 Bedroom + Living Room + Kitchen + 2 Toilets + 2 Flowered Area + Dry Balcony. (1 BHK) The property is at 5.2 Km. distance from railway station Vasai Road
6	Locatio	n of property		
a)	Plot No	. / Survey No.	:	Survey No - 63/2/1, 64/2, 277/3 & 278/1
b)	Door N	0.	:	Residential Flat No. 1204
			•	



Vastukala Consultants (I) Pvt. Ltd.

			Villago Cokhivara					
c)	C.T.S. No. / Village	:	Village - Gokhivare					
d)	Ward / Taluka	:	Taluka - Vasai					
e)	Mandal / District	:	District - Palghar					
f)	Date of issue and validity of layout of approved map / plan	:	As Occupancy Certificate is re that the construction is as per					
g)	Approved map / plan issuing authority	:						
h)	Whether genuineness or authenticity of approved map/ plan is verified	:	No					
i)	Any other comments by our empanelled valuers on authentic of approved plan	:	No					
7	Postal address of the property	:	Flat No. 1204, Basement Floor "Agarwal Exotica Co-op. Hs Smart City, Sector/Area. 1, Vill Vasai, District - Palghar, Vasa Maharashtra, India.	ig. Soc. Ltd. ", Yashwant lage - Gokhivare, Taluka -				
8	City / Town		City - Vasai (East)					
	Residential area	:/	Yes					
	Commercial area		No					
	Industrial area	:	No					
9	Classification of the area							
	i) High / Middle / Poor		Middle Class					
	ii) Urban / Semi Urban / Rura		Urban					
10	Coming under Corporation limit / Village Panchayat / Municipality	:	Village - Gokhivare Thane Municipal Corporation					
11	Whether covered under any State / Central Govt. enactments (e.g., Urban Land Ceiling Act) or notified under agency area/ scheduled area / cantonment area	:	No					
12	Boundaries of the property	:	A - As per site	B - As per Document				
	North	:	open plot	Internal Road & Open Plot				
	South	:	Dosti pine	Internal Road & PIL Tower				
	East	/	Dosti Cedar	Meera Avenue				
	West Think.Inne	D١		Internal Road				
13	Dimensions of the site	:	N. A. as property under consid in a building.	leration is a Residential Flat				
		:	A - As per the Deed	B - Actuals				
	North	:	-	-				
	South	:	-	-				
	East	:	-					
	West	:	-	-				

4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available . Lift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes III Residential Flat . Yes	5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available . . Lift : 2
5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Ift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage 12. Parting - Open / Covered : covered is compound wall existing? 13. Foresting - Open / Covered : vertex covered is pavement laid around the Building	5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available . . Lift : 2
6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2
6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : Z Protected Water Supply : Municipal Water Supply : Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered : Is Compound wall existing? : No : Is pavement laid around the Building : Yes Yes	6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available
7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2 Lift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available . . Lift : 2
7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2 Lift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available . . Lift : 2
7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2 Lift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available . . Lift : 2
7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2 Lift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available . . Lift : 2
7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2 Lift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available . . Lift : 2
7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2 Lift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available . . Lift : 2
7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2 Lift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available . . Lift : 2
7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2 Lift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available . . Lift : 2
7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2 Lift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available . . Lift : 2
7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2 Lift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available . . Lift : 2
7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2 Lift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available . . Lift : 2
6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2
6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2
6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2
5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Ift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage 12. Parting - Open / Covered : covered is compound wall existing? 13. Foresting - Open / Covered : vertex covered is pavement laid around the Building	5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available . . Lift : 2
5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Ift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage 12. Parting - Open / Covered : covered is compound wall existing? 13. Foresting - Open / Covered : vertex covered is pavement laid around the Building	5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available . . Lift : 2
5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Ift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage 12. Parting - Open / Covered : covered is compound wall existing? 13. Foresting - Open / Covered : vertex covered is pavement laid around the Building	5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available . . Lift : 2
5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Ift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage 12. Parting - Open / Covered : covered is compound wall existing? 13. Foresting - Open / Covered : vertex covered is pavement laid around the Building	5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available . . Lift : 2
5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Ift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage 12. Parting - Open / Covered : covered is compound wall existing? 13. Foresting - Open / Covered : vertex covered is pavement laid around the Building	5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available . . Lift : 2
5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Ift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage 12. Parting - Open / Covered : covered is compound wall existing? 13. Foresting - Open / Covered : vertex covered is pavement laid around the Building	5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available . . Lift : 2
5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Ift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage 12. Parting - Open / Covered : covered is compound wall existing? 13. Foresting - Open / Covered : vertex covered is pavement laid around the Building	5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available . . Lift : 2
5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Ift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage 12. Parking - Open / Covered : covered 13. Scompound wall existing? : No	5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available . . Lift : 2
5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Ift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage 12. Parking - Open / Covered : covered 13. Scompound wall existing? : No	5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available . . Lift : 2
4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2
4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2
Commercial / MixedCommercial / Mixed4.Year of Construction:2020 (As per occupancy certificate)5.Number of Floors:Part Ground + Part Stilt + 14 Upper Floors6.Type of Structure:R.C.C. Framed Structure Structure7.Number of Dwelling units in the building:Basement Floor is having 4 Flats8.Quality of Construction:Good9.Appearance of the Building:Good10.Maintenance of the Building:Good11.Facilities Available:Lift12.Protected Water Supply:Municipal Water Supply13.Underground Sewerage:Connected to Municipal Sewerage System14.Car parking - Open / Covered:covered15.S pavement laid around the Building:Yes	Commercial / Mixed2020 (As per occupancy certificate)4.Year of Construction:2020 (As per occupancy certificate)5.Number of Floors:Part Ground + Part Stilt + 14 Upper Floors6.Type of Structure:R.C.C. Framed Structure Structure7.Number of Dwelling units in the building:Basement Floor is having 4 Flats8.Quality of Construction:Good9.Appearance of the Building:Good10.Maintenance of the Building:Good11.Facilities Available:2
Commercial / MixedCommercial / Mixed4.Year of Construction:2020 (As per occupancy certificate)5.Number of Floors:Part Ground + Part Stilt + 14 Upper Floors6.Type of Structure:R.C.C. Framed Structure Structure7.Number of Dwelling units in the building:Basement Floor is having 4 Flats8.Quality of Construction:Good9.Appearance of the Building:Good10.Maintenance of the Building:Good11.Facilities Available:Lift12.Protected Water Supply:Municipal Water Supply13.Underground Sewerage:Connected to Municipal Sewerage System14.Car parking - Open / Covered:covered15.S pavement laid around the Building:Yes	Commercial / Mixed2020 (As per occupancy certificate)4.Year of Construction:2020 (As per occupancy certificate)5.Number of Floors:Part Ground + Part Stilt + 14 Upper Floors6.Type of Structure:R.C.C. Framed Structure Structure7.Number of Dwelling units in the building:Basement Floor is having 4 Flats8.Quality of Construction:Good9.Appearance of the Building:Good10.Maintenance of the Building:Good11.Facilities Available:2
Commercial / Mixed 2020 (As per occupancy certificate) 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available	Commercial / Mixed2020 (As per occupancy certificate)4.Year of Construction:2020 (As per occupancy certificate)5.Number of Floors:Part Ground + Part Stilt + 14 Upper Floors6.Type of Structure:R.C.C. Framed Structure Structure7.Number of Dwelling units in the building:Basement Floor is having 4 Flats8.Quality of Construction:Good9.Appearance of the Building:Good10.Maintenance of the Building:Good11.Facilities Available:2
3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Ift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered : sovered Is compound wall existing? : No is pavement laid around the Building : Yes	3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2
3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Ift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered : sovered Is compound wall existing? : No is pavement laid around the Building : Yes	3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2
Maharashtra, India. 3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available	Maharashtra, India. 3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available
Maharashtra, India.3.Description of the locality Residential / Commercial / Mixed:Residential4.Year of Construction:2020 (As per occupancy certificate)5.Number of Floors:Part Ground + Part Stilt + 14 Upper Floors6.Type of Structure:R.C.C. Framed Structure Structure7.Number of Dwelling units in the building:Basement Floor is having 4 Flats8.Quality of Construction:Good9.Appearance of the Building:Good10.Maintenance of the Building:Good11.Facilities Available:2Protected Water Supply:Municipal Water SupplyUnderground Sewerage:Connected to Municipal Sewerage SystemCar parking - Open / Covered:coveredIs pavement laid around the Building:Yes	Maharashtra, India. 3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Ift : 2
3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Ift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered : No Is pavement laid around the Building : Yes Yes	Maharashtra, India. 3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2
Vasai , District - Palghar, Vasai (East), 401 208, State - Maharashtra, India.3.Description of the locality Residential / Commercial / Mixed:Residential4.Year of Construction:2020 (As per occupancy certificate)5.Number of Floors:Part Ground + Part Stilt + 14 Upper Floors6.Type of Structure:R.C.C. Framed Structure Structure7.Number of Dwelling units in the building:Basement Floor is having 4 Flats8.Quality of Construction:Good9.Appearance of the Building:Good10.Maintenance of the Building:Good11.Facilities AvailableI12.Lift:213.Protected Water Supply:Municipal Water Supply14.Underground Sewerage:covered15.Sayment laid around the Building:No	Vasai , District - Palghar, Vasai (East), 401 208, State - Maharashtra, India.3.Description of the locality Residential / Commercial / Mixed:Residential4.Year of Construction:2020 (As per occupancy certificate)5.Number of Floors:Part Ground + Part Stilt + 14 Upper Floors6.Type of Structure:R.C.C. Framed Structure Structure7.Number of Dwelling units in the building:Basement Floor is having 4 Flats8.Quality of Construction:Good9.Appearance of the Building:Good10.Maintenance of the Building:Good11.Facilities Available:22.Lift:2
Vasai , District - Palghar, Vasai (East), 401 208, State - Maharashtra, India. 3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Ift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : covered Is Compound wall existing? : No : No	Vasai , District - Palghar, Vasai (East), 401 208, State - Maharashtra, India. 3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Lift : 2
Vasai , District - Palghar, Vasai (East), 401 208, State - Maharashtra, India. 3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Ift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : covered Is Compound wall existing? : No : No	Vasai , District - Palghar, Vasai (East), 401 208, State - Maharashtra, India. 3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Lift : 2
Vasai , District - Palghar, Vasai (East), 401 208, State - Maharashtra, India. 3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Ift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : covered Is Compound wall existing? : No : No	Vasai , District - Palghar, Vasai (East), 401 208, State - Maharashtra, India. 3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Lift : 2
Maharashtra, India.3.Description of the locality Residential / Commercial / Mixed:Residential4.Year of Construction:2020 (As per occupancy certificate)5.Number of Floors:Part Ground + Part Stilt + 14 Upper Floors6.Type of Structure:R.C.C. Framed Structure Structure7.Number of Dwelling units in the building:Basement Floor is having 4 Flats8.Quality of Construction:Good9.Appearance of the Building:Good10.Maintenance of the Building:Good11.Facilities Available:212.Protected Water Supply:Municipal Water Supply13.Underground Sewerage:Connected to Municipal Sewerage System14.Is compound wall existing?:No15.Is pavement laid around the Building:Yes	Vasai , District - Palghar, Vasai (East), 401 208, State - Maharashtra, India. 3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Lift : 2
Vasai , District - Palghar, Vasai (East), 401 208, State - Maharashtra, India. 3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Ift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : covered Is Compound wall existing? : No : No	Vasai , District - Palghar, Vasai (East), 401 208, State - Maharashtra, India. 3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Lift : 2
Vasai , District - Palghar, Vasai (East), 401 208, State - Maharashtra, India. 3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Ift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : covered Is Compound wall existing? : No : Yes No	Vasai , District - Palghar, Vasai (East), 401 208, State - Maharashtra, India. 3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available
Vasai , District - Palghar, Vasai (East), 401 208, State - Maharashtra, India. 3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Ift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : covered Is Compound wall existing? : No : Yes No	Vasai , District - Palghar, Vasai (East), 401 208, State - Maharashtra, India. 3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available
Vasai , District - Palghar, Vasai (East), 401 208, State - Maharashtra, India. 3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Ift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : covered Is Compound wall existing? : No : Yes No	Vasai , District - Palghar, Vasai (East), 401 208, State - Maharashtra, India. 3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available
Vasai , District - Palghar, Vasai (East), 401 208, State - Maharashtra, India. 3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Ift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : covered Is Compound wall existing? : No : Yes No	Vasai , District - Palghar, Vasai (East), 401 208, State - Maharashtra, India. 3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available
Maharashtra, India.3.Description of the locality Residential / Commercial / Mixed:Residential4.Year of Construction:2020 (As per occupancy certificate)5.Number of Floors:Part Ground + Part Stilt + 14 Upper Floors6.Type of Structure:R.C.C. Framed Structure Structure7.Number of Dwelling units in the building:Basement Floor is having 4 Flats8.Quality of Construction:Good9.Appearance of the Building:Good10.Maintenance of the Building:Good11.Facilities Available:2Protected Water Supply:Municipal Water SupplyUnderground Sewerage:Connected to Municipal Sewerage SystemCar parking - Open / Covered:coveredIs pavement laid around the Building:Yes	Maharashtra, India. 3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Ift : 2
Maharashtra, India. 3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available	Maharashtra, India. 3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available
Maharashtra, India. 3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available	Maharashtra, India. 3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available
Maharashtra, India. 3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available	Maharashtra, India. 3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available
Maharashtra, India. 3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available	Maharashtra, India. 3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available
Maharashtra, India. 3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available	Maharashtra, India. 3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available
3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Ift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered : No Is pavement laid around the Building : Yes Yes	3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2
3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Ift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered : No Is pavement laid around the Building : Yes Yes	3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2
3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Ift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered : No Is pavement laid around the Building : Yes Yes	3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2
3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Ift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered : No Is pavement laid around the Building : Yes Yes	3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2
3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Ift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered : No Is pavement laid around the Building : Yes Yes	3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2
3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Ift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered : No Is pavement laid around the Building : Yes Yes	3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2
3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Ift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered : No Is pavement laid around the Building : Yes Yes	3. Description of the locality Residential / Commercial / Mixed : Residential 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2
Commercial / Mixed2020 (As per occupancy certificate)4.Year of Construction:2020 (As per occupancy certificate)5.Number of Floors:Part Ground + Part Stilt + 14 Upper Floors6.Type of Structure:R.C.C. Framed Structure Structure7.Number of Dwelling units in the building:Basement Floor is having 4 Flats8.Quality of Construction:Good9.Appearance of the Building:Good10.Maintenance of the Building:Good11.Facilities Available:Image: Connected to Municipal Sewerage System12.Protected Water Supply:Municipal Water Supply13.Underground Sewerage:Connected to Municipal Sewerage System14.Car parking - Open / Covered:covered15.S pavement laid around the Building:Yes	Commercial / Mixed 2020 (As per occupancy certificate) 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Image: Construction is constructin is construction is construction is construction is construction
Commercial / Mixed2020 (As per occupancy certificate)4.Year of Construction:2020 (As per occupancy certificate)5.Number of Floors:Part Ground + Part Stilt + 14 Upper Floors6.Type of Structure:R.C.C. Framed Structure Structure7.Number of Dwelling units in the building:Basement Floor is having 4 Flats8.Quality of Construction:Good9.Appearance of the Building:Good10.Maintenance of the Building:Good11.Facilities Available:Image: Connected to Municipal Sewerage System12.Protected Water Supply:Municipal Water Supply13.Underground Sewerage:Connected to Municipal Sewerage System14.Car parking - Open / Covered:covered15.S pavement laid around the Building:Yes	Commercial / Mixed 2020 (As per occupancy certificate) 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Image: Construction is constructin is construction is construction is construction is construction
Commercial / Mixed2020 (As per occupancy certificate)4.Year of Construction:2020 (As per occupancy certificate)5.Number of Floors:Part Ground + Part Stilt + 14 Upper Floors6.Type of Structure:R.C.C. Framed Structure Structure7.Number of Dwelling units in the building:Basement Floor is having 4 Flats8.Quality of Construction:Good9.Appearance of the Building:Good10.Maintenance of the Building:Good11.Facilities Available:Image: Connected to Municipal Sewerage System12.Protected Water Supply:Municipal Water Supply13.Underground Sewerage:Connected to Municipal Sewerage System14.Car parking - Open / Covered:covered15.S pavement laid around the Building:Yes	Commercial / Mixed 2020 (As per occupancy certificate) 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Image: Construction is constructin is construction is construction is construction is construction
Commercial / Mixed2020 (As per occupancy certificate)4.Year of Construction:2020 (As per occupancy certificate)5.Number of Floors:Part Ground + Part Stilt + 14 Upper Floors6.Type of Structure:R.C.C. Framed Structure Structure7.Number of Dwelling units in the building:Basement Floor is having 4 Flats8.Quality of Construction:Good9.Appearance of the Building:Good10.Maintenance of the Building:Good11.Facilities Available:Image: Connected to Municipal Sewerage System12.Protected Water Supply:Municipal Water Supply13.Underground Sewerage:Connected to Municipal Sewerage System14.Car parking - Open / Covered:covered15.S pavement laid around the Building:Yes	Commercial / Mixed 2020 (As per occupancy certificate) 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Image: Construction is constructin is construction is construction is construction is construction
Commercial / Mixed2020 (As per occupancy certificate)4.Year of Construction:2020 (As per occupancy certificate)5.Number of Floors:Part Ground + Part Stilt + 14 Upper Floors6.Type of Structure:R.C.C. Framed Structure Structure7.Number of Dwelling units in the building:Basement Floor is having 4 Flats8.Quality of Construction:Good9.Appearance of the Building:Good10.Maintenance of the Building:Good11.Facilities Available:Image: Connected to Municipal Sewerage System12.Protected Water Supply:Municipal Water Supply13.Underground Sewerage:Connected to Municipal Sewerage System14.Car parking - Open / Covered:covered15.S pavement laid around the Building:Yes	Commercial / Mixed 2020 (As per occupancy certificate) 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Image: Construction is constructin is construction is construction is construction is construction
Commercial / Mixed2020 (As per occupancy certificate)4.Year of Construction:2020 (As per occupancy certificate)5.Number of Floors:Part Ground + Part Stilt + 14 Upper Floors6.Type of Structure:R.C.C. Framed Structure Structure7.Number of Dwelling units in the building:Basement Floor is having 4 Flats8.Quality of Construction:Good9.Appearance of the Building:Good10.Maintenance of the Building:Good11.Facilities Available:Image: Connected to Municipal Sewerage System12.Protected Water Supply:Municipal Water Supply13.Underground Sewerage:Connected to Municipal Sewerage System14.Car parking - Open / Covered:covered15.S pavement laid around the Building:Yes	Commercial / Mixed 2020 (As per occupancy certificate) 4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Image: Construction is constructin is construction is construction is construction is construction
Commercial / MixedCommercial / Mixed4.Year of Construction:2020 (As per occupancy certificate)5.Number of Floors:Part Ground + Part Stilt + 14 Upper Floors6.Type of Structure:R.C.C. Framed Structure Structure7.Number of Dwelling units in the building:Basement Floor is having 4 Flats8.Quality of Construction:Good9.Appearance of the Building:Good10.Maintenance of the Building:Good11.Facilities Available:Lift12.Protected Water Supply:Municipal Water Supply13.Underground Sewerage:Connected to Municipal Sewerage System14.Car parking - Open / Covered:covered15.S pavement laid around the Building:Yes	Commercial / Mixed2020 (As per occupancy certificate)4.Year of Construction:2020 (As per occupancy certificate)5.Number of Floors:Part Ground + Part Stilt + 14 Upper Floors6.Type of Structure:R.C.C. Framed Structure Structure7.Number of Dwelling units in the building:Basement Floor is having 4 Flats8.Quality of Construction:Good9.Appearance of the Building:Good10.Maintenance of the Building:Good11.Facilities Available:2
4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2
4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2
4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	4. Year of Construction : 2020 (As per occupancy certificate) 5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2
5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Ift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage 12. Parking - Open / Covered : covered 13. Scompound wall existing? : No	5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2
5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Ift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage 12. Parking - Open / Covered : covered 13. Scompound wall existing? : No	5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2
5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available . Lift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2
5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available . Lift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2
5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available . Lift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2
5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Ift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage 12. Parking - Open / Covered : covered 13. Scompound wall existing? : No	5. Number of Floors : Part Ground + Part Stilt + 14 Upper Floors 6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2
6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available image: Structure : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2
6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2
6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : Z Protected Water Supply : Municipal Water Supply : Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered : Is Compound wall existing? : No : Is pavement laid around the Building : Yes Yes	6. Type of Structure : R.C.C. Framed Structure Structure 7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available
7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available
7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2 Lift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	7. Number of Dwelling units in the building : Basement Floor is having 4 Flats 8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available . . Lift : 2
8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : Cood Lift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Image: Construction : Lift : 2
8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : Good Lift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Image: Construction : Lift : 2
8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : Good Lift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	8. Quality of Construction : Good 9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available Image: Construction : Lift : 2
9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2 Lift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2
9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2 Lift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2
9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available : 2 Lift : : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	9. Appearance of the Building : Good 10. Maintenance of the Building : Good 11. Facilities Available
10. Maintenance of the Building Good Good 11. Facilities Available Image: Constant of the Supply Lift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	10. Maintenance of the Building Good Good 11. Facilities Available Image: Create Lift : 2
10. Maintenance of the Building Good Good 11. Facilities Available Image: Constant of the Supply Lift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	10. Maintenance of the Building Good Good 11. Facilities Available Image: Create Lift : 2
10. Maintenance of the Building Good Good 11. Facilities Available Image: Constant of the Supply Lift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	10. Maintenance of the Building Good Good 11. Facilities Available Image: Create Lift : 2
11. Facilities Available Image: Constraint of the state of th	11. Facilities Available Lift :
11. Facilities Available Image: Constraint of the state of th	11. Facilities Available Lift :
Lift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	Lift : 2
Lift : 2 Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	Lift : 2
Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	
Protected Water Supply : Municipal Water Supply Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	
Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	Protected Water Supply
Underground Sewerage : Connected to Municipal Sewerage System Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	I Protected Water Supply I - I Municipal Water Supply
Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	
Car parking - Open / Covered : covered Is Compound wall existing? : No Is pavement laid around the Building : Yes	Underground Sewerage
Is Compound wall existing? : No Is pavement laid around the Building : Yes	Underground Sewerage : Connected to Municipal Sewerage System
Is Compound wall existing? : No Is pavement laid around the Building : Yes	
Is pavement laid around the Building : Yes	
Is pavement laid around the Building : Yes	Car parking - Open / Covered : covered
Is pavement laid around the Building : Yes	Car parking - Open / Covered : covered
	Car parking - Open / Covered : covered
III Residential Flat	Is Compound wall existing? : No
III Residential Flat	Is Compound wall existing? : No
	Is Compound wall existing? : No
	Is Compound wall existing? : No
	Is Compound wall existing? : No Is pavement laid around the Building : Yes
1. The floor in which the Flat is situated : Basement Floor	Is Compound wall existing? : No Is pavement laid around the Building : Yes



Vastukala Consultants (I) Pvt. Ltd.

2.	Door No. of the Flat	:	Residential Flat No. 1204
3.	Specifications of the Flat		
	Roof	:	R. C. C. Slab
	Flooring	:	Italian Marble Flooring
	Doors	:	Teak Wood Door frame with Solid flush door
	Windows	:	Powder coated Aluminum sliding windows
	Fittings	:	Concealed plumbing with C.P. fittings. Electrical wiring with concealed
	Finishing	:	Cement Plastering with POP false Celling
4.	House Tax		
	Assessment No.	:	Details not available
	Tax paid in the name of	:	Details not available
	Tax amount	:	Details not available
5.	Electricity Service connection No.	:	Details not available
	Meter Card is in the name of	:/	Details not available
6.	How is the maintenance of the Flat?		Good
7.	Sale Deed executed in the name of		Mr. Amit Kumar & Mrs. Nisha Shersingh Adhikari
8.	What is the undivided area of land as per Sale Deed?	:	Details not available
9.	What is the plinth area of the Flat?	:	Built Up Area in Sq. Ft. = 474.10 (Carpet Area + 10%)
10.	What is the floor space index (app.)	:	As per VVCMC norms
11.	What is the Carpet area of the Flat?	:	Carpet Area in Sq. Ft. = 431.00 (As Per Area Agreement for sale) Carpet Area in Sq. Ft. = 440.66 (As per Area actual site measurement)
12.	Is it Posh / I Class / Medium / Ordinary?	:	Medium
13.	Is it being used for Residential or Commercial purpose?	:	Residential
14.	Is it Owner-occupied or let out?		Vacant
15.	If rented, what is the monthly rent?	01	₹ 22000 (Present rented income as per month)
IV	MARKETABILITY		
1.	How is the marketability?	:	Good
2.	What are the factors favoring for an extra Potential Value?	:	Details not available
3.	Any negative factors are observed which affect the market value in general?	:	Details not available
V	Rate		
1.	After analyzing the comparable sale instances, what is the composite rate for a similar Flat with same specifications in the adjoining locality? - (Along with details / reference of at - least two latest deals / transactions with respect to adjacent properties in the areas)	:	₹ 9,400.00 to ₹ 10,600.00 per Sq. Ft. on Built Up
	ł		4



2.	Assuming it is a new construction, what is the adopted basic composite rate of the Flat under valuation after comparing with the specifications and other factors with the Flat under comparison (give details).	:	₹ 10,500.00 per Sq. Ft.
3.	Break – up for the rate	:	
	I. Building + Services	:	₹ 2,600.00 per Sq. Ft.
	II. Land + others	:	₹ 7,900.00 per Sq. Ft.
4.	Guideline rate obtained from the Registrar's Flat for new property (an evidence thereof to be enclosed)	:	₹ 0.00 per Sq. M. i.e. ₹ 0.00 per Sq. Ft.
5.	In case of variation of 20% or more in the valuation proposed by the Valuer and the Guideline value provided in the State Govt. notification or Income Tax Gazette justification on variation has to be given	:	It is a foregone conclusion that market value is always more than the RR price. As the RR Rates area Fixed by respective State Government for computing Stamp Duty / Rgstn. Fees. Thus the differs from place to place and Location, Amenities per se as evident from the fact than even RR Rates Decided by Government Differs.
VI	COMPOSITE RATE ADOPTED AFTER DEPRECIATION		
а	Depreciated building rate		
	Replacement cost of Flat with Services (v(3)i)		₹ 2,600.00 per Sq. Ft.
	Age of the building		2 years
	Life of the building estimated	:	58 years Subject to proper, preventive periodic maintenance & structural repairs.
	Depreciation percentage assuming the salvage value as 10%	:	N.A. Age of Property below 5 year
	Depreciation Ratio of the building		-
b	Total composite rate arrived for Valuation		
	Depreciated building rate VI (a)	:	₹ 2,600.00 per Sq. Ft.
	Rate for Land & other V (3) ii	÷	₹ 7,900.00 per Sq. Ft.
	Total Composite Rate	:	₹ 10500 per Sq. Ft.
	Remarks	:	

Details of Valuation:

Sr. No.	Description	novate.Cre Qty.	Rate per unit (₹)	Est. Value (₹)
1	Present value of the Flat (incl. car parking, if provided)	431.00 Sq. Ft.	10,500.00	45,25,500.00
2	Wardrobes			
3	Showcases			
4	Kitchen arrangements			
5	Superfine finish			
6	Interior Decorations			
7	Electricity deposits / electrical fittings, etc.			
8	Extra collapsible gates / grill works, etc.			



9	Potential value, if any		
10	Others		
	Total / Realizable value of the property	45,25,500.00	
	Insurable value of the property	12,32,400.00	
	Guideline value of the property	0.00	

Justification for Price / Rate

The Market Value of the property is based on facts of markets discovered by us during our enquiries, however the government rate value in this case is less than the market value arrived by us. We are of the opinion that the value arrive by us will prove to be correct if an Auction of the subject property is carried out. As far as Market Value in Index II is concerned, it is not possible to comment on same, may be government rates are fixed by sampling during same point of time in part and whereas, Market values change every month.

In most of the cases the actual deal amount or Transaction value is not reflected in Index II because of various Market practices. As Valuer, we always try to give a value which is correct reflection of actual transaction value irrespective of any factors in market.

Method of Valuation / Approach

The sales comparison approach uses the market data of sale prices to estimate the value of a real estate property. Property valuation in this method is done by comparing a property to other similar properties that have been recently sold. Comparable properties, also known as comparables, or comps, must share certain features with the property in question. Some of these include physical features such as square footage, number of rooms, condition, and age of the building; however, the most important factor is no doubt the location of the property. Adjustments are usually needed to account for differences as no two properties are exactly the same. To make proper adjustments when comparing properties, real estate appraisers must know the differences between the comparable properties and how to value these differences. The sales comparison approach is commonly used for Residential Flat, where there are typically many comparables available to analyze. As the property is a Residential Flat, we have adopted Sale Comparison Approach Method for the purpose of valuation .The Price for similar type of property in the nearby vicinity is in the range of ₹ 9,400.00 to ₹ 10,600.00 per Sq. Ft. on Built Up Area. Considering the rate with attached report, current market conditions, demand and supply position, Flat size, location, upswing in real estate prices, sustained demand for Residential Flat, all round development of commercial and Commercial application in the locality etc. We estimate 10,500.00 per Sq. Ft. for valuation.

Impending threat of acquisition by government for roa CRZ provisions (Distance from sea-cost / tidal level mu		
Saleability		Good
Likely rental values in future		₹ 22000 (Present rented income as per month)
Any likely income it may generate		Rental Income
lhink.ln	novate.	Create



Vastukala Consultants (I) Pvt. Ltd.

Actual Site Photographs








Think.Innovate.Create



Route Map of the property



Note:Red marks shows the exact location of the property



Longitude Latitude: 19°23'41.7"N 72°50'58.9"E

Note: The Blue line shows the route to site from nearest railway station (Vasai Road - 5.2 Km.).





Ready Reckoner Rate

4		t of Registratic		amps	नोंदप		मुद्रांक ाष्ट्र शार	ं विभाग तन	Ð	
		नोंदणी व	-	वेभाग, महा रूप दर पत्रक	राष्ट्र श	ासन				
Home	Val	uation Rules User	Manual					<u>Close</u>	Feed	back
Year 20222023 ¥	Selected District	Ann पालघर	ual Sta ~	tement of	Rate	5				Language English V
	Select Taluka Select Village	वसई गावाचे नांव - मौजे गोर	∽ बीवरे]	~]				
	Search By Enter Survey No	Survey No OL	ocation Searc	:h						
	उपविभाग		खुली जमीन	निवासी सदनिका	ऑफ़ीस	दुकाने	औद्योगिक	(resu)	Attribute	
	2/1-रहिवास व इतर त	गातील जमिनी त्सम अनुज्ञेय वापरातील मेनी	2860 14000	0 72500	0 82800	0 90600	0 82800	चौ. मीटर चौ. मीटर		



Think.Innovate.Create








Page 12 of 24

Price Indicator

Residential Flat
https://www.99acres.com/
Carpet
474
10%
₹ 11,076.00



Vastukala Consultants (I) Pvt. Ltd. An ISO 9001:2015 Certified Company



www.vastukala.org

Flat
https://www.99acres.com/
Carpet
365
10%
₹ 10,521.00

Home > Property for Sale in Mumbal > Fla	its for Sale in Mumbai > Flats fo	or Sale in Vasai East ⇒1 BHK Flats for :	Sale in Vasai East > 478 Sq-ft		Posted on: Nov 29, 22 Property ID: 638
₹38.4 Lac <u>Get ₹11</u>			ΤΕ	:	Contact Agent
1 BHK 478 Sq-ft Flat For S	ale Vasai East, Mumb	bai			Ayodha Parsad Singh
		음 1Bed 관 2Ba	ths 🛗 3 Balconies [Unfurnished	
migic		Carpet Area	Developer	Project	Your Name
	A 100	365 sqft * ₹10,527/sqft	Agarwal Group	Agarwal Exotica	
		Floor	Transaction Type	Status	Email
	6	5 (Out of 14 Floors)	New Property	Ready to Move	Email ID field can't be left blank. Please enter!
	+11 Photos	Facing	Lifts	Furnished Status	
East Facing Property	0	East	2	Unfurnished	IND +91 Y Mobile Number
					Get Contact Details
More Details					
Price Breakup	₹38.4 Lac ₹1,92,	125 Approx. Registration	Charges		We can visit this property on your behalf
Booking Amount	₹ 51,000				Simply tell us the details you wish to know
Address	-	, Yashwant Smart City, oad and Beyond, Mah		ownship, Vasai East,	LIVE video tour
Landmarks	Vasai East				Verified Property details
Furnishing	Unfurnished				Verified Photos & videos
					See How it Works →



Property	flat
Source	https://www.99acres.com/
Area Type	Carpet
Area	366
Percentage	10%
Rate / Sq. feet on BuiltUp area	₹ 11,694.00
Floor	

					Posted on: Nov 29, 22 Property I
₹42.8 Lac <u>Get ₹</u>	12,847 cashback on Ho	me Loan VERIFIED ON	ISITE		: Contact Agent
1 BHK 366 Sq-ft Flat For	r Sale Agarwal Exotica,	Yashwant Smar, Mumba	1		Certified Agent Ayodha Parsad Singh
		음 1Bed 괸 1Ba	ath 🛛 🏦 3 Balconies 🛛 🗄] Unfurnished	-91-93300000087
and the second se		Carpet Area	Developer	Project	Your Name
		366 sqft * ₹11,701/sqft	Agarwal Group	Agarwal Exotica	Name field can't be left blank. Plea enter your name!
191		Floor	Transaction Type	Status	
	E	13 (Out of 14 Floors)	New Property	Ready to Move	Email
	+9 Photos	Facing	Lifts 2	Furnished Status Unfurnished	Email ID field can't be left blank. Pi enter!
 East Facing Property 	ty 🕑 Newly Construct	ted Property			Mobile Number
Contact Agent	Get Phone No.				IND +91 V
Contact Agent More Details Price Breakup					I Agree to MagicBricks' <u>Terms of U</u> Cet Contact Details We can visit this propert
More Details					I Agree to MagicBricks' <u>Terms of Us</u> <u>Get Contact Details</u> We can visit this property your behalf Simply tell us the details you
More Details Price Breakup	₹42.8 Lac ₹51,000	ıbai., Vasai East, Muml	bai - Mira Road and Be	yond, Maharashtra	I Agree to MegicBricks' <u>Terms of Us</u> Get Contact Details We can visit this property your behalf Simply tell us the details you to know
More Details Price Breakup Booking Amount	₹42.8 Lac ₹51,000	nbai., Vasai East, Mumi	bai - Mira Road and Be	yond, Maharashtra	I Agree to MagicBricks' <u>Terms of Us</u> Cet Contact Details We can visit this property your behalf Simply tell us the details your to know D LIVE video tour
More Details Price Breakup Booking Amount Address	₹42.8 Lac ₹51,000 Vasai East, Murr	ıbal,, Vasai East, Muml	bai - Mira Road and Be	yond, Maharashtra	I Agree to MagicBricks' <u>Terms of Us</u> <u>Get Contact Details</u> <u>We can visit this property</u> <u>your behalf</u> Simply tell us the details your to know
More Details Price Breakup Booking Amount Address Landmarks	₹42.8 Lac ₹51,000 Vasai East, Mum Vasai east.	nbai., Vasai East, Mumi	bai - Mira Road and Be	ryond, Maharashtra	I Agree to MagicBricks' <u>Terms of Us</u> Cet Contact Details We can visit this property your behalf Simply tell us the details your to know D LIVE video tour

Vastukala Consultants (I) Pvt. Ltd.

Sale Instances

Property	Flat
Source	https://www.99acres.com/
Area Type	Built Up
Area	403.00
Rate / Sq. feet on BuiltUp area	₹ 3807000 per Sq. Ft.
Floor	

907533	सुची क्र.2	ৰুব্বদ নিৰ্জ্যক : सह বু.বি.বমৰ্ছ 4
01/12/2022		रस्त ज्ञमांक : 907/2022
Note:-Generated Through eSearch		नोदंगी :
Module, For original report please contact concern SRO office.		Regn:63m
	गावाचे नाव : गोखिवरे	•
(1)हिल्लेखाच्य प्रकार	गावाच नाव : गा।रपुष र करारनामा	¢
(2)गोवदाना	3807000	
(3) वाजरभाव(भारेपटरवाच्या वावतितपटराकार	2232000	
(.)) या सरमाय(माध्यस्था जा यायामायस्थाजन आवारणी देतो की चटटेवर ते नमुद करावे)	2232000	
(4) भू-नावन,चोटडिस्मा व पग्ठानांक(अमल्याम)	अगरवाल एक्झोटीका,बिल्डींग र्व. 7, ब्लॉक सदनिकेचे क्षेत्र 34.04 ची. मी. कारपेट + 5	ा नं: 1004,डी विंग, माळा नं: दहावा मजला, इमारतीचे नाव: नं: बशवंत स्मार्ट सिटी,सेक्टर- 1, रोड : गोखिवरे, इतर माहिती: 5.96 ची. मी. बाल्कनी,नाव मौजे गोखिवरे,विभाग क्र. 2.((
	Survey Number : 63, 64, 277,	278;))
(5) ਦੇਸ਼ਦਰ	37.44 चौ.मीटर	
(6)आकारणी किंवा जुडी देण्यात असेल तेव्हा.		
(7) कतरेवत्र कान देशा-वा/तिहून डेवला-वा पक्षकागथे नाव किंवा दिवाणी न्यावालयाथा हुकुमनाना किंवा आयेत असल्यास,प्रतिवाहिये नाव व पता.		की एल. अगरबाल तर्फे कु.मु. फिल प्रतिष नाईक - बन:-39 पत्त:-प्लॉट मं: प्र बिल्डींग , ब्लॉक मं: -, पोड मं: अगरबाल गार्डन, फेन्न -2, गोकुळ ठॉक्नलीप, 303 पंत मं:-AAPFA7627Q
(8)वस्तरेखन करून पेणा-या घडकरापे व किंवा दिखणी न्यायालयपा हुकुबनाया किंवा आरेज असान्यास,प्रतिवाहिये नाव व एता	क्लॉक नं: -, रोड नं: यूंवाबन कॉम्पलेक्स, एवटरताईन गेट ASQPT0512Q 2): नाव:-विन वीपक तिवारी वष:-32; पता:-/	-प्लॉट में: प्लॉट में. 12, ए सिंग, माला में: -, इसलीचे मातः साधेगोल्ड किल्डीप , समई पूर्व, निरुदा पालमर, पडालपट, ठानें: पिन कोड:-401208 पंग में:- प्लॉट में: कर्नट में: 12, ए सिंग, पाळा में: -, इसालीचे नाजः साणिगोल्ड किल्डीप, , समई पूर्व, निरुदा पालमर, पडालपट, ठाने. पिन कोड:-401208 पंग में:-
(9) दस्तरोग्रज करून दिल्याचा दिनांक	24/01/2022	
(10)वस्त नोंदणी केल्याचा दिनांक	24/01/2022	
(11)अनुक्रमांक,खंड व यृष्ट	907/2022	
(12)बाजरभावप्रधाने युद्धंक मुल्क	228500	
(13)वाजरभावात्रमाने नोंदनी मुल्क	30000	
(14)m		
मुल्यांकनासाठी विष्यागत चेठलेला त्र्यशील:-:		
मुदांक मुल्क आकारताना निवडलेला अनुष्पडेद :- :	(i) within the limits of any Mu area annexed to it.	unicipal Corporation or any Cantonment
	area annexed to it.	01-12



Justification for price / rate

The Market Value of the property is based on facts of markets discovered by us during our enquiries, however the government rate value in this case is less than the market value arrived by us. We are of the opinion that the value arrive by us will prove to be correct if an Auction of the subject property is carried out. As far as Market Value in Index II is concerned, it is not possible to comment on same, may be government rates are fixed by sampling during same point of time in part and whereas, Market values change every month.

In most of the cases the actual deal amount or Transaction value is not reflected in Index II because of various Market practices. As Valuer, we always try to give a value which is correct reflection of actual transaction value irrespective of any factors in market.

We hope this will satisfy your requirements.

As a result of my appraisal and analysis, it is my considered opinion that of the above property in the prevailing condition with aforesaid specifications is ₹45,25,500.00 (Rupees Forty Five Lakh Twenty Five Thousand Five Hundred Only Only).

Place : Mumbai Date : 03.12.2022

For VASTUKALA CONSULTANTS (I) PVT. LTD.

\sim		R	ù	Π		Г	٦	
C	ŝ	ľ	۷	1	•	Ļ	,	•

Director



Manoj Chalikwar Govt. Reg. Valuer Chartered Engineer (India) Reg. No. IBBI/RV/07/2018/10366 SBI Empanelment No.: SME/TCC/2021-22/86/3

The unde	ersigned has inspected the property detailed in the Valuation Report dated	on
	We are satisfied that the fair and reasonable market value of the property is ₹	
(Rupees _	Think.Innovate.Create only).	

Date____

Signature (Name & Designation of the Inspecting Official/s)

Countersigned (BRANCH MANAGER)

Enclosures	
Declaration-cum-undertaking from the valuer (Annexure-IV)	Attached
Model code of conduct for valuer - (Annexure V)	Attached



(Annexure-IV)

DECLARATION-CUM-UNDERTAKING

- I, Manoj Chalikwar son of Shri. Baburao Chalikwar do hereby solemnly affirm and state that:
 - a. I am a citizen of India.
 - b. I will not undertake valuation of any assets in which I have a direct or indirect interest or become so interested at any time during a period of three years prior to my appointment as valuer or three years after the valuation of assets was conducted by me.
 - c. The information furnished in my valuation report dated 03.12.2022 is true and correct to the best of my knowledge and belief and I have made an impartial and true valuation of the property.
 - d. I/my authorized representative have personally inspected the property on . The work is not sub contracted to any other valuer and carried out by myself.
 - e. Valuation report is submitted in the format as prescribed by the bank.
 - f. I have not been depanelled / delisted by any other bank and in case any such depanelment by other banks during my empanelment with you, I will inform you within 3 days of such depanelment.
 - g. I have not been removed / dismissed from service / employment earlier.
 - h. I have not been convicted of any offence and sentenced to a term of imprisonment
 - i. I have not been found guilty of misconduct in my professional capacity.
 - j. I have not been declared to be unsound mind
 - k. I am not an undischarged bankrupt, or has not applied to be adjudicated as a bankrupt;
 - I. I am not an undischarged insolvent.
 - m. I have not been levied a penalty under section 271J of Income-tax Act, 1961 (43 of 1961) and time limit for filing appeal before Commissioner of Income-tax (Appeals) or Income-tax Appellate Tribunal, as the case may be has expired, or such penalty has been confirmed by Income-tax Appellate Tribunal, and five years have not elapsed after levy of such penalty
 - n. I have not been convicted of an offence connected with any proceeding under the Income Tax Act 1961, Wealth Tax Act 1957 or Gift Tax Act 1958 and
 - o. My PAN Card number as applicable is AERPC9086P
 - p. I undertake to keep you informed of any events or happenings which would make me ineligible for empanelment as a valuer
 - q. I have not concealed or suppressed any material information, facts and records and I have made a complete and full disclosure
 - r. I have read the Handbook on Policy, Standards and procedure for Real Estate Valuation, 2011 of the IBA and this report is in conformity to the 'Standards' enshrined for valuation in the Part B of the above handbook to the best of my ability.
 - s. I have read the International Valuation Standards (IVS) and the report submitted to the Bank for the respective asset class is in conformity to the 'Standards' as enshrined for valuation in the IVS in 'General Standards' and 'Asset Standards' as applicable. The valuation report is submitted in the prescribed format of the bank.
 - t. I abide by the Model Code of Conduct for empanelment of valuer in the Bank. (Annexure V A signed copy of same to be taken and kept along with this declaration)

- v. My CIBIL Score and credit worthiness is as per Bank's guidelines.
- w. I am competent to sign this valuation report.





- x. I will undertake the valuation work on receipt of Letter of Engagement generated from the system (i.e. LLMS / LOS) only.
- y. Further, I hereby provide the following information.

No.	Particulars	Valuer comment				
1	background information of the asset being valued;	The property under consideration is purchased by Mr. Amit Kumar & Mrs. Nisha Shersingh Adhikari from M/s. Agarwal Realtors vide Agreement for sale dated 24/11/2022.				
2	purpose of valuation and appointing authority	As per the request from State Bank of India, RASMECCC Bhayandar to assess Fair Market Value value of the property for Bank Loan purpose				
3	identity of the valuer and any other experts involved in the valuation;	Manoj Chalikwar - ® Regd. Valuer Chandan Singh - ® Valuation Engineer Shobha Kuperkar - ® Technical Manager Shamal Bodke - ® Technical Officer				
4	disclosure of valuer interest or conflict, if any;	We have no interest, either direct or indirect, in the property valued. Further to state that we do not have relation or any connection with property owner / applicant directly or indirectly. Further to state that we are an independent Valuer and in no way related to property owner / applicant				
5	date of appointment, valuation date and date of report;	Date of Appointment - 03.12.2022 Valuation Date - 03.12.2022 Date of Report - 03.12.2022				
6	inspections and/or investigations undertaken;	Physical Inspection done on -				
7	nature and sources of the information used or relied upon;	Market Survey at the time of site visit Ready Reckoner rates / Circle rates Online search for Registered Transactions Online Price Indicators on real estate portals Enquiries with Real estate consultants Existing data of Valuation assignments carried out by us				
8	Procedures adopted in carrying out the valuation and valuation standards followed;	Sales Comparative Method				
9	restrictions on use of the report, if any;	This valuation is for the use of the party to whom it is addressed and for no other purpose. No responsibility is accepted to any third party who may use or rely on the whole or any part of this valuation. The valuer has no pecuniary interest that would conflict with the proper valuation of the property.				
10	major factors that were taken into account during the valuation; Think.In	current market conditions, demand and supply position, Residential Flat size, location, upswing in real estate prices, sustained demand for Residential Flat, all round development of commercial and Commercial application in the locality etc.				
11	major factors that were not taken into account during the valuation;	-				
12	Caveats, limitations and disclaimers to the extent they explain or elucidate the limitations faced by valuer, which shall not be for the purpose of limiting his responsibility for the valuation report.	Attached				

Vastukala Consultants (I) Pvt. Ltd. An ISO 9001:2015 Certified Company



www.vastukala.org

Assumptions, Disclaimers, Limitations & Qualifications

Value Subject to Change

The subject appraisal exercise is based on prevailing market dynamics as on **3rd December 2022** and does not take into account any unforeseeable developments which could impact the same in the future.

Our Investigations

We are not engaged to carry out all possible investigations in relation to the subject property. Where in our report we identify certain limitations to our investigations, this is to enable the reliant party to instruct further investigations where considered appropriate or where we recommend as necessary prior to reliance. Vastukala Consultants India Pvt. Ltd. (VCIPL) is not liable for any loss occasioned by a decision not to conduct further investigations.

Assumptions

Assumptions are a necessary part of undertaking valuations. VCIPL adopts assumptions for the purpose of providing valuation advice because some matters are not capable of accurate calculations or fall outside the scope of our expertise, or out instructions. The reliant party accepts that the valuation contains certain specific assumptions and acknowledge and accept the risk of that if any of the assumptions adopted in the valuation are incorrect, then this may have an effect on the valuation.

Information Supplied by Others

The appraisal is based on the information provided by the client. The same has been assumed to be correct and has been used for appraisal exercise. Where it is stated in the report that another party has supplied information to VCIPL, this information is believed to be reliable but VCIPL can accept no responsibility if this should prove not to be so.

Future Matters

To the extent that the valuation includes any statement as to a future matter, that statement is provided as an estimate and/or opinion based on the information known to VCIPL at the date of this document. VCIPL does not warrant that such statements are accurate or correct.

Map and Plans

Any sketch, plan or map in this report is included to assist the reader while visualising the property and assume no responsibility in connection with such matters.

Site Details

Based on inputs received from Client's representative and site visit conducted, we understand that the subject property is Residential Flat, admeasuring **431.00 Sq. Ft. Carpet Area** in the name of **Mr. Amit Kumar & Mrs. Nisha Shersingh Adhikari**. Further, VCIPL has assumed that the subject property is free from any encroachment and is available as on the date of the appraisal.

Property Title

Based on our discussion with the Client, we understand that the subject property is owned by **Mr. Amit Kumar & Mrs. Nisha Shersingh Adhikari**. For the purpose of this appraisal exercise, we have assumed that the subject property has a clear title and is free from any encumbrances, disputes and claims. VCIPL has made no further enquiries with the relevant local authorities in this regard and does not certify the property as having a clear and marketable title. Further, no legal advice regarding the title and ownership of the subject property has been obtained for the purpose of this appraisal exercise. It has been assumed that the title deeds are clear and marketable.



Page 20 of 24

Environmental Conditions

We have assumed that the subject property is not contaminated and is not adversely affected by any existing or proposed environmental law and any processes which are carried out on the property are regulated by environmental legislation and are properly licensed by the appropriate authorities.

Area

Based on the information provided by the Client's representative, we understand that the Residential Flat, admeasuring **431.00 Sq. Ft. Carpet Area**.

Condition & Repair

In the absence of any information to the contrary, we have assumed that there are no abnormal ground conditions, nor archaeological remains present which might adversely affect the current or future occupation, development or value of the property. The property is free from rat, infestation, structural or latent defect. No currently known deleterious or hazardous materials or suspect techniques will be used in the construction of or subsequent alteration or additions to the property and comments made in the property details do not purport to express an opinion about, or advise upon, the condition of uninspected parts and should not be taken as making an implied representation or statement about such parts.

Valuation Methodology

For the purpose of this valuation exercise, the valuation methodology used is Direct Comparison Approach Method and proposed Highest and Best Use model is used for analysing development potential.

In case of inadequate recent transaction activity in the subject micro-market, the appraiser would collate details of older transactions. Subsequently, the appraiser would analyse rental / capital value trends in the subject micro-market in order to calculate the percentage increase / decrease in values since the date of the identified transactions. This percentage would then be adopted to project the current value of the same.

Where reliance has been placed upon external sources of information in applying the valuation methodologies, unless otherwise specifically instructed by Client and/or stated in the valuation, VCIPL has not independently verified that information and VCIPL does not advise nor accept it as reliable. The person or entity to whom the report is addressed acknowledges and accepts the risk that if any of the unverified information in the valuation is incorrect, then this may have an effect on the valuation.

Not a Structural Survey

We state that this is a valuation report and not a structural survey.

Other

Think.Innovate.Create

All measurements, areas and ages quoted in our report are approximate.

Legal

We have not made any allowances with respect to any existing or proposed local legislation relating to taxation on realization of the sale value of the subject property. VCIPL is not required to give testimony or to appear in court by reason of this appraisal report, with reference to the property in question, unless arrangement has been made thereof. Further, no legal advice on any aspects has been obtained for the purpose of this appraisal exercise.

Property specific assumptions

Based on inputs received from the client and site visit conducted, we understand that the subject property is **Residential Flat**, admeasuring **431.00 Sq. Ft. Carpet Area.**





ASSUMPTIONS, CAVEATS, LIMITATION AND DISCLAIMERS

- 1. We assume no responsibility for matters of legal nature affecting the property appraised or the title thereto, nor do we render our opinion as to the title, which is assumed to be good and marketable.
- 2. The property is valued as though under responsible ownership.
- 3. It is assumed that the property is free of liens and encumbrances
- 4. It is assumed that there are no hidden or unapparent conditions of the subsoil or structure that would render it more or less valuable. No responsibility is assumed for such conditions or for engineering that might be required to discover such factors.
- 5. There is no direct/ indirect interest in the property valued.
- 6. The rates for valuation of the property are in accordance with the Govt. approved rates and prevailing market rates.

Think.Innovate.Create



(Annexure-II)

MODEL CODE OF CONDUCT FOR VALUERS

Integrity and Fairness

- 1. A valuer shall, in the conduct of his/its business, follow high standards of integrity and fairness in all his/its dealings with his/its clients and other valuers.
- 2. A valuer shall maintain integrity by being honest, straightforward, and forthright in all professional relationships.
- 3. A valuer shall endeavour to ensure that he/it provides true and adequate information and shall not misrepresent any facts or situations.
- 4. A valuer shall refrain from being involved in any action that would bring disrepute to the profession.
- 5. A valuer shall keep public interest foremost while delivering his services.

Professional Competence and Due Care

- 6. A valuer shall render at all times high standards of service, exercise due diligence, ensure proper care and exercise independent professional judgment.
- 7. A valuer shall carry out professional services in accordance with the relevant technical and professional standards that may be specified from time to time.
- 8. A valuer shall continuously maintain professional knowledge and skill to provide competent professional service based on up-to-date developments in practice, prevailing regulations / guidelines and techniques.
- 9. In the preparation of a valuation report, the valuer shall not disclaim liability for his/its expertise or deny his/its duty of care, except to the extent that the assumptions are based on statements of fact provided by the company or its auditors or consultants or information available in public domain and not generated by the valuer.
- 10. A valuer shall not carry out any instruction of the client insofar as they are incompatible with the requirements of integrity, objectivity and independence.
- 11. A valuer shall clearly state to his client the services that he would be competent to provide and the services for which he would be relying on other valuers or professionals or for which the client can have a separate arrangement with other valuers.

Independence and Disclosure of Interest

- 12. A valuer shall act with objectivity in his/its professional dealings by ensuring that his/its decisions are made without the presence of any bias, conflict of interest, coercion, or undue influence of any party, whether directly connected to the valuation assignment or not.
- 13. A valuer shall not take up an assignment if he/it or any of his/its relatives or associates is not independent in terms of association to the company.
- 14. A valuer shall maintain complete independence in his/its professional relationships and shall conduct the valuation independent of external influences.
- 15. A valuer shall wherever necessary disclose to the clients, possible sources of conflicts of duties and interests,



while providing unbiased services

- 16. A valuer shall not deal in securities of any subject company after any time when he/it first becomes aware of the possibility of his / its association with the valuation, and in accordance with the Securities and Exchange Board of India (Prohibition of Insider Trading)Regulations,2015 or till the time the valuation report becomes public, whichever is earlier.
- 17. A valuer shall not indulge in 'mandate snatching' or offering 'convenience valuations' in order to cater to a company or client's needs.
- 18. As an independent valuer, the valuer shall not charge success fee.
- 19. In any fairness opinion or independent expert opinion submitted by a valuer, if there has been a prior engagement in an unconnected transaction, the valuer shall declare the association with the company during the last five years.

Confidentiality

20. A valuer shall not use or divulge to other clients orany other party any confidential information about the subject company, which has come to his / itsknowledge without proper and specific authority or unless there is a legal or professional right or duty to disclose.

Information Management

- 21. A valuer shall ensure that he/ it maintains written contemporaneous records for any decision taken, the reasons for taking the decision, and the information and evidence in support of such decision. This shall be maintained so as to sufficiently enable a reasonable person to take a view on the appropriateness of his /its decisions and actions.
- 22. A valuer shall appear, co-operate and be available for inspections and investigations carried out by the authority, any person authorised by the authority, the registered valuers organisation with which he/it is registered or any other statutory regulatory body.
- 23. A valuer shall provide all information and records as may be required by the authority, the Tribunal, Appellate Tribunal, the registered valuers organisation with which he/it is registered, or any other statutory regulatorybody.
- 24. A valuer while respecting the confidentiality of information acquired during the course of performing professional services, shall maintain proper working papers for a period of three years or such longer period as required in its contract for a specific valuation, for production before a regulatory authority or for a peer review. In the event of a pending case before the Tribunal or Appellate Tribunal, the record shall be maintained till the disposal of the case.

Gifts and hospitality:

- 25. A valuer or his / its relative shall not accept gifts or hospitality which undermines or affects his independence as a valuer.Explanation: For the purposes of this code the term 'relative' shall have the same meaning as defined in clause (77) of Section 2 of the Companies Act, 2013 (18 of 2013).
- 26. valuer shall not offer gifts or hospitality or a financial or any other advantage to a public servant or any other person with a view to obtain or retain work for himself / itself, or to obtain or retain an advantage in the conduct of profession for himself / itself.





Remuneration and Costs.

- 27. A valuer shall provide services for remuneration which is charged in a transparent manner, is a reasonable reflection of the work necessarily and properly undertaken, and is not inconsistent with the applicable rules.
- 28. A valuer shall not accept any fees or charges otherthan those which are disclosed in a written contract with the person to whom he would be rendering service.

Occupation, employability and restrictions

- 29. A valuer shall refrain from accepting too many assignments, if he/it is unlikely to be able to devote adequate time to each of his/ its assignments.
- 30. A valuer shall not conduct business which in the opinion of the authority or the registered valuer organisation discredits the profession.

Miscellaneous

- 31. A valuer shall refrain from undertaking to review the work of another valuer of the same client except under written orders from the bank or housing finance institutions and with knowledge of the concerned valuer.
- 32. A valuer shall follow this code as amended or revised from time to time.

Manoj Chalikwar

Govt. Reg. Valuer Chartered Engineer (India) Reg. No. IBBI/RV/07/2018/10366 SBI Empanelment No.: SME/TCC/2021-22/86/3

Think.Innovate.Create

